

AD-A098 560

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON --ETC F/G 13/13  
NATIONAL DAM SAFETY PROGRAM. MORRIS LAKE DAM (NJ00306). HUDSON --ETC(U)  
MAR 81 P K YU DACW61-79-C-0011

UNCLASSIFIED

DAEN/NAP-53842/NJ00306-81/ NL

1 OF 1  
AD-A098 560


END

DATE

FILMED

18-81

DTIC




AD A098560

HUDSON RIVER BASIN  
TRIBUTARY OF WALLKILL RIVER  
SUSSEX COUNTY  
NEW JERSEY

# MORRIS LAKE DAM

## NJ 00306

### PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



DTIC  
ELECTE

MAY 6 1981

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.

DTIC FILE COPY

DEPARTMENT OF THE ARMY

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania


Rept. no. DAEN/NAP-53842/NJ00306-81/03

MARCH 1981

81 5 04 086

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER DAEN/NAP 53842/NJ00306-81/03Y	2. GOVT ACCESSION NO. AD-A098560	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Morris Lake Dam (NJ00306), Sussex County, NJ	5. TYPE OF REPORT & PERIOD COVERED FINAL	
7. AUTHOR(s) K. Peter/Yo P.E.	8. CONTRACT OR GRANT NUMBER(s) DACW61-79-C-0011	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Langan Engineering Associates, Inc. 990 Clifton Ave. Clifton, N.J. 07013	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 12	
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CNO29 Trenton, NJ 08625	12. REPORT DATE March 1981	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106	13. NUMBER OF PAGES 65	
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Embankments Visual Inspection Structural Analysis National Dam Safety Program Morris Lake Dam, N.J. Spillways Seepage		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE-2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO  
NAPEN-N

24 APR 1981

Honorable Brendan T. Byrne  
Governor of New Jersey  
Trenton, New Jersey 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Morris Lake Dam in Sussex County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Morris Lake Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 51 percent of the Probable Maximum Flood would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. The following remedial actions should be initiated within three months from the date of approval of this report:

(1) Perform additional investigation to determine seepage conditions through and under the dam, the engineering properties of the dam and foundation, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and, what modifications may be required to achieve such safety margins.

(2) Provide emergency low level outlets for the dam.

(3) Repair areas of spalled and deteriorated concrete on the dam appurtenances.

(4) Investigate the cause of cracking and separation and repair the facing on the downstream side of the dam.

NAPEN-N

Honorable Brendan T. Byrne

c. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.


d. An emergency action plan should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within three months from the date of approval of this report.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Courter of the Thirteenth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

1 Incl  
As stated

**Copies furnished:**

Mr. Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief  
Bureau of Flood Plain Regulation  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

Transmittal For	
GRA&I	<input checked="checked" type="checkbox"/>
TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
Distribution/	
Date	
By	

A

MORRIS LAKE DAM (NJ00306)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 12 September and 1 December 1980 by Langan Engineering Associates, Inc. under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Morris Lake Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 51 percent of the Probable Maximum Flood would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. The following remedial actions should be initiated within three months from the date of approval of this report:

(1) Perform additional investigation to determine seepage conditions through and under the dam, the engineering properties of the dam and foundation, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and, what modifications may be required to achieve such safety margins.

(2) Provide emergency low level outlets for the dam.

(3) Repair areas of spalled and deteriorated concrete on the dam appurtenances.

(4) Investigate the cause of cracking and separation and repair the facing on the downstream side of the dam.

c. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.

d. An emergency action plan should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within three months from the date of approval of this report.

APPROVED: 

JAMES G. TON

Colonel, Corps of Engineers  
District Engineer

DATE: 21 April 1981



**PHASE I INSPECTION REPORT**  
**NATIONAL DAM SAFETY PROGRAM**

NAME OF DAM:	MORRIS LAKE DAM
ID NUMBER:	FED ID No NJ 00306
STATE LOCATED:	NEW JERSEY
COUNTY LOCATED:	SUSSEX
STREAM:	TRIBUTARY OF WALLKILL RIVER
RIVER BASIN:	HUDSON
DATE OF INSPECTION:	SEPTEMBER & DECEMBER 1980

ASSESSMENT OF GENERAL CONDITIONS

→ Morris Lake dam, classified under high hazard potential category, is in fair overall condition. The structural stability of the dam is uncertain. The concrete gunite facing on the downstream face of the dam has numerous large cracks and is separating from the dam in areas. There is seepage through one of the cracks. Spalling and deteriorating concrete exist at a number of locations on the upstream and downstream face of the dam, and are particularly severe at the east upstream abutment and on the spillway wingwall near the west abutment. The condition of the original masonry dam within the present dam is unknown. There is no emergency low level outlet for the dam. There is no engineering data available concerning the design or construction of the original dam or subsequent modifications. The spillway capacity as determined by the Corps of Engineers screening criteria is inadequate. The dam can adequately pass only 50% of the ~~PMP~~<sup>PMP</sup> *probable maximum flood*.

→ The following are recommended to be done soon:

→ Perform additional investigation to determine seepage conditions through and under dam, the engineering properties of the dam and foundation, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and, what modifications may be required to achieve such safety margins. Provide emergency low level outlet for the dam. Repair areas of spalled and deteriorated concrete on the dam appurtenances.

*Page - B -*

Rept. no. DAEN/NAP -53842/NJ 00306 -81/03

The following are recommended to be done in the near future:

Investigate the cause of cracking and separation and repair the facing on the downstream side of the dam. Establish a warning system and develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam. The spillway capacity is estimated to be inadequate. The capacity of the spillway and SDF should be determined using more precise and sophisticated methods and procedures.

  
K. Peter Yu, P.E.



OVERALL VIEW  
MORRIS LAKE DAM

12 September 1980

**PHASE I INSPECTION REPORT**  
**NATIONAL DAM SAFETY PROGRAM**

<b>NAME OF DAM:</b>	<b>MORRIS LAKE DAM</b>
<b>ID NUMBER:</b>	<b>FED ID No NJ 00306</b>
<b>STATE LOCATED:</b>	<b>NEW JERSEY</b>
<b>COUNTY LOCATED:</b>	<b>SUSSEX</b>
<b>STREAM:</b>	<b>TRIBUTARY OF WALLKILL RIVER</b>
<b>RIVER BASIN:</b>	<b>HUDSON</b>
<b>DATE OF INSPECTION:</b>	<b>SEPTEMBER &amp; DECEMBER 1980</b>



**LANGAN ENGINEERING ASSOCIATES, INC.**

**Consulting Civil Engineers**  
**990 CLIFTON AVENUE**  
**CLIFTON, NEW JERSEY**  
**201-472-9366**

CONTENTS  
NATIONAL DAM SAFETY REPORT  
MORRIS LAKE DAM FED ID NO NJ 00306

	<u>PAGE</u>
PREFACE	
SECTION 1 PROJECT INFORMATION	
1.1 General	1
1.2 <u>Project Description</u>	1
1.3 <u>Pertinent Data</u>	3
SECTION 2 ENGINEERING DATA	
2.1 <u>Design</u>	5
2.2 <u>Construction</u>	5
2.3 <u>Operation</u>	6
2.4 <u>Evaluation</u>	6
SECTION 3 VISUAL INSPECTION	6
SECTION 4 OPERATIONAL PROCEDURES	6
SECTION 5 HYDRAULIC/HYDROLOGIC	7
SECTION 6 STRUCTURAL STABILITY	7
SECTION 7 ASSESSMENT, RECOMMENDATIONS/ REMEDIAL MEASURES	
7.1 <u>Dam Assessment</u>	8
7.2 <u>Recommendations/Remedial Measures</u>	8
FIGURES	
1. Regional Vicinity Map	
2. Morris Lake Dam: Plan, Profile and Section	
APPENDICES	
1. Check List, Hydrologic & Hydraulic Data Check List, Visual Inspection Check List, Engineering Data	
2. Photographs	
3. Hydrologic Computations	
4. Notes on Newton, New Jersey Water Works Construction and Litigation	
5. References	

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

## SECTION 1 PROJECT INFORMATION

### 1.1 General

Authority to perform the Phase I Safety Inspection of Morris Lake Dam was received from the State of New Jersey Department of Environmental Protection, Division of Water Resources by letter dated 12 August 1980. This Authority was given pursuant to the National Dam Inspection Act, Public Law 92-367 and by agreement between the State and the US Army Engineers District, Philadelphia.

The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to safety of Morris Lake Dam and appurtenances based upon available data and visual inspection, and determine any need for emergency measures and conclude if additional studies, investigations and analyses are necessary and warranted. The assessment is made using screening criteria established in Recommended Guidelines for Safety Inspection of Dams prepared by the Department of Army, Office of the Chief of Engineers. It is not the purpose of the inspection report to imply that a dam meeting or failing to meet the screening criteria is, per se, certainly adequate or inadequate.

### 1.2 Project Description

#### a. Description of Dam and Appurtenances

Morris Lake Dam is a concrete faced stone masonry gravity structure with an overall length of dam and appurtenances of approximately 205 feet and an effective length of 160 feet. The dam is reported to have a vertical upstream face and a 2 vertical to 1 horizontal downstream face. The main axis of the dam is slightly concave downstream and is oriented in a east-west direction separating the upstream Morris Lake and the downstream Glen Lake. Based on available information, the original dam was constructed of granitic rock. At a latter date the dam was raised several feet to its present level and the stone masonry dam was faced with an unknown thickness of reinforced concrete (gunite) on the upstream side and approximately 1 1/2 inches of unreinforced concrete on the downstream side. The top of the dam is approximately 5 feet wide. The dam is reported to have a maximum height of 38 feet and to be founded on the bedrock. The depths from top of dam to upstream and downstream lake bottom measured in the center of the dam are approximately 15 feet.

The spillway has a broad crested weir of trapezoidal cross section and it exists in the form of a rectangular opening near the west abutment of the dam. The opening measures approximately 2 feet high and 14 feet wide with the base located approximately 3.2 feet below the top of the dam. It is reported that stop logs have been used in the past to increase the storage elevation of the dam.

A gatehouse exists on the crest of the dam about 1/3 of its length from the east abutment.

There are presently two outlet pipes, of 12 inch and 16 inch diameter, existing through the dam below the gatehouse. Both pipes are water supply mains for the Town of Newton and a small portion of the Town of Sparta. Based on conversations with the dam's caretaker, the normal daily consumption rate is 800,000 gallons per day.

A more elaborate description of the water works for the reservoir is included in Appendix 4.

b. Location

Morris Lake Dam is located at the southern end of Morris Lake and the northern end of Glen Lake in Sparta, Sussex County, New Jersey. It is located at north latitude  $41^{\circ}02.6'$  and west longitude  $74^{\circ}36.5'$ . A regional vicinity map is given in Fig. 1.

c. Size Classification

The maximum storage capacity of Morris Lake Dam is estimated to be 2,985 ac ft. The dam is classified as intermediate in size based on this storage capacity which is more than 1,000 ac ft but less than 50,000 ac ft. The dam is classified as small based on its maximum height of 38 feet which is less than 40 feet. Accordingly the dam is classified as "Intermediate" in size.

d. Hazard Classification

Morris Lake Dam is listed as having a "High" Hazard potential on the National Inventory of Dams. The downstream potential damage centers of Sparta Glen, a recreation area, and the northern portion of the Town of Sparta are located approximately  $1/2$  and  $1\ 1/2$  miles from the dam. Based on visual inspection of the downstream area, a failure of Morris Lake Dam would result a surge of water into Glen Lake immediately downstream thus causing possible overtopping and failure of Glen Lake Dam, which in turn would result in flooding of Sparta Glen, and possibly the northern portion of Sparta. This represents a potential for more than a few loss of lives. Accordingly, it is recommended to keep the Hazard Potential Classification for Morris Lake Dam as "High".

e. Ownership

Ownership of Morris Lake Dam is by The Town of Newton, 39 Trinity Street, Newton, New Jersey.

f. Purpose of Dam

The purpose of the dam is public water supply for the Town of Newton and a small portion of the Town of Sparta.



g. **Design and Construction History**

Based on conversations with Town of Newton officials and published reports, the construction history of Morris Lake Dam is believed to be as follows:

The dam was originally constructed in 1894-1895 as a stone masonry dam for the purpose of water supply. The dam was engineered by Louis L. Tribus, of New York, New York and constructed by Smith and McCormick. In 1927, apparently due to seepage of water through the dam, the upstream face of the dam was covered with a thickness of up to one foot of reinforced concrete (reported to be gunite) and the downstream face with a 1 to 1 1/2 inch thick coating of unreinforced concrete.

At this time, the existing gatehouse was added and the dam raised several feet. Engineering for the Gatehouse was performed by William J. Hardin and construction was performed by John W. Heller, Co. In 1929 a new water intake was installed in the lake. Engineering for this new intake was by the firm of Tribus and Massa and constructed by Merritt, Chapman and Scott Corp., New York.

Also in this time period a 20 inch diversion pipeline was installed between the head gate at Pine Swamp Brook and Morris Lake which replaced a diversion channel constructed in 1895. This diversion pipe is used only during dry periods when the level of Morris Lake drops to the point of not adequately servicing the water needs of the Town of Newton. In 1976 a 16 inch water supply pipe was installed through a former 24 inch low level outlet, thereby eliminating an emergency low level outlet for the dam.

h. **Normal Operational Procedures**

Based on conversations with representatives of The Newton Department of Water, operational procedures are the following:

Chlorine and fluoride are added at the Gatehouse prior to the water entering the 12 and 16 inch water supply pipelines. Daily lake level readings are taken to depth of water below spillway. Daily records of water flow through the pipelines are maintained.

1.3 **Pertinent Data**

a. **Drainage Areas**

1.07 sq mi for Morris Lake under normal conditions.  
3.5 sq. mi. when head gates at Pine Swamp Brook are opened during dry periods.

b. **Discharge at Damsite**

Maximum known flood at damsite

unknown

Ungated spillway capacity at max. pool elev.

283 cfs (Assumed top of dam.

c.	<u>Elevation (ft. above MSL)</u>	
	Top of Dam	942.8
	Maximum pool-design surcharge	unknown
	Spillway crest	939.6
	Streambed at centerline of dam	928±
	Maximum tailwater	Unknown. Approx. el 930.8 at time of inspection
d.	<u>Reservoir</u>	
	Length of maximum pool	Approx 3,450 ft
	Length of normal pool	Approx 3,400 ft
e.	<u>Storage (acre-feet)</u>	
	Normal pool	Approx 2,470 ac ft
	Top of dam	Approx 2,985 ac ft
f.	<u>Reservoir Surface (acres)</u>	
	Top dam	Approx 165
	Maximum pool	Approx 165 (Assumes top of dam)
	Normal pool	Approx 157 (Assumed to be spillway crest)
	Spillway crest	Approx 157
g.	<u>Dam</u>	
	Type	Concrete faced stone masonry gravity
	Length	160 ft
	Height	15 ft (top of dam to downstream streambed) 38 ft (top of dam to Bedrock)
	Top Width	Approx 5 ft
	Side Slopes	U/S vertical D/S 2V:1H

Zoning	Unknown
Impervious Core	Unknown
Cutoff	Foundation reported to be on bedrock
Grout curtain	None reported
h. <u>Spillway</u>	
Type	Broad crested trapazoidal weir
Length of weir	14 ft
Crest elevation	939.6 ft MSL
Gates	None
U/S Channel	Vertical face
D/S Channel	1H to 2V
i. <u>Regulating Outlets</u>	
	12" water supply main 16" water supply main

## SECTION 2 ENGINEERING DATA

### 2.1 Design

No engineering design data pertaining to engineering values, calculation or test results for the original structure or subsequent modifications have been found.

### 2.2 Construction

The available data pertaining to the construction and modifications of the dam and appurtenances known to exist and to be possessed by the town of Newton, New Jersey are:

Engineer's Final Report on Construction of the Newton, New Jersey Water Works dated November 30, 1895 by Louis L. Tribus.

Notes on Newton, New Jersey Water Works Construction and Litigation by Louis L. Tribus, New England Water Works Association, Vol XXIII, No. 2, June 1909, included in Appendix 4.

Survey, 20" Cast Iron Pipe Line in Morris Lake, Sussex County, New Jersey for Newton Water Works by Tribus and Massa, September 1929.

### 2.3 Operations

There is a full time resident at the dam. The resident reportedly makes daily visual examinations of the dam and appurtenances as part of his daily duties, together with his performance of items given in normal operational procedures.

### 2.4 Evaluation

Available information concerning the engineering properties of the dam and foundation materials and materials used in subsequent modifications is not adequate to evaluate the design and construction of the dam.

## SECTION 3 VISUAL INSPECTION

Morris Lake Dam is in fair overall condition. The gunite facing on the downstream face of the dam has numerous large cracks. The gunite surface below the cracks appears to have separated from the body of the dam. Weeds are growing in many of these cracks. There is limited seepage from a crack in the gunite surface approx 10' below the top of the dam in the area of the gatehouse. There are bulges in the gunite surface on the downstream face at the water line. The upstream face of the dam, where visible, has occasional areas of spalling and cracking of the gunite surface. The concrete forming the east abutment is spalled and deteriorating on the upstream face. The concrete downstream wingwall on the west side of the spillway is extensively spalled and deteriorated.

The gatehouse appears in good general condition with all equipment reported in operable condition.

Conversations with a representative of the Newton Department of Water revealed the original 24 inch diameter low level outlet had been used as a sleeve for the installation of the 16-inch water main, thereby eliminating the low level outlet.

The reservoir is surrounded by forested watershed areas.

Immediately downstream of the dam is Glen Lake. Morris Lake Dam separates Morris Lake from Glen Lake.

## SECTION 4 OPERATIONAL PROCEDURES

General operational procedures for the dam include daily recordings of water main flow, fluoridation and chlorination of water and periodic cleaning of the water supply intake screens. There is a full time resident of the Newton Department of Water living at the damsite.

No formal warning system is in effect.

## SECTION 5 HYDRAULIC/HYDROLOGIC

The hydraulic/hydrologic evaluation is based on a Spillway Design Flood (SDF) equal to the probable maximum flood chosen in accordance with the evaluation guidelines for dams classified as high hazard and intermediate in size. Hydrologic design data for this dam was not available. The PMF has been determined by developing a synthetic hydrograph based on the probable maximum precipitation of 22.3 inches (200 sq. mi.-24 hour). The Corps of Engineers has recommended the use of the SCS triangular unit hydrograph with the curvilinear transformation. Hydrologic computations are presented in Appendix 3. The PMF inflow determined for the subject watershed is 4,533 cfs (routed to 1,545 cfs).

The capacity of the spillway at maximum pool elevation (942.8) is 283 cfs which is significantly less than the SDF. Flood routing indicates the dam will overtop by 1.92 ft for the PMF and will not overtop for the 1/2 PMF. We estimate the dam can adequately pass only 50% of the PMF.

The present outlet structures consist of one 12 inch CIP and one 16 inch RCP which deliver potable water to the town of Newton. No emergency low level outlet exists.

## SECTION 6 STRUCTURAL STABILITY

Our visual observations indicate no evidence of immediate instability of the dam exist under normal operating conditions. However, the actual degree of stability is not certain. No information is available concerning the engineering properties of the foundation and dam materials. The stone masonry forming the original dam is not visible due to the gunite surfacing and its condition is unknown. The gunite surfacing on the downstream face of the dam has numerous large cracks and appears to have separated from the dam in various areas. Seepage through cracks was observed during inspection.

No design data is available for the original dam or subsequent modifications made in 1927 and 1929.

Operating records pertain to daily flows through the 12 inch and 16 inch water supply pipelines only.

There is inadequate design and construction information to determine the actual degree of stability of the dam using present day state of the art methods.

Morris Lake dam is located in Seismic Zone I of the Seismic Zone map of Contiguous States. The degree of stability of the dam and appurtenances under static loading are uncertain with respect to conventional safety margins and may be unstable under earthquake loading. Its actual structural stability should be evaluated using state of the art methods when additional relevant information becomes available.

## SECTION 7 ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

### 7.1 Dam Assessment

Morris Lake dam is in fair overall condition. The structural stability of the dam is uncertain. The concrete gunite facing on the downstream face of the dam has numerous large cracks and is separating from the dam in areas. Seepage was observed through one of the cracks during inspection. Spalling and deteriorating concrete exist at a number of locations on the upstream and downstream face of the dam and are particularly severe at the east upstream abutment and on the spillway wingwall near the west abutment. The condition of the original masonry dam within the present dam is unknown. There is no emergency low level outlet for the dam. There is no engineering data available concerning the design or construction of the original dam or subsequent modifications. The spillway capacity as determined by the Corps of Engineers Screening criteria is inadequate. The spillway can adequately pass only 50% of the PMF.

### 7.2 Recommendations/Remedial Measures


The following are recommended to be done soon:

1. Perform additional investigation to determine seepage conditions through and under the dam, the engineering properties of the dam and foundation, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and, what modifications may be required to achieve such safety margins.
2. Provide emergency low level outlets for the dam.
3. Repair areas of spalled and deteriorated concrete on the dam appurtenances.

The following are recommended to be done in the near future:

1. Investigate the cause of cracking and separation and repair the facing on the downstream side of the dam.
2. Establish a warning system and develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.
3. The spillway capacity is estimated to be inadequate. The capacity of the spillway and SDF should be determined using more precise and sophisticated methods and procedures.

## FIGURES



BY \_\_\_\_\_ DATE \_\_\_\_\_

CKD \_\_\_\_\_ DATE \_\_\_\_\_

REGIONAL VICINITY MAP

MORRIS LAKE

JOB NO. 80145

SCALE: 1" = 2 miles FIG. No. 1



E 2,016,100  
N 805,000

947

945

940

SHORELINE 8/2


BO


1/21/74

N 805,000  
E 2,016,400

# MORRIS LAKE


WATER ELEV. 936.4 12 SEPT. 80





NOTES:

1. THIS PLAN WAS ADAPTED FROM DRAWING PREPARED BY  
CAHN ENGINEERS, INC., WALLINGFORD, CONNECTICUT, MORRIS  
LAKE DAM, DAM PLAN, PROFILE & SECTION, MARCH 1979



4

# GLEN LAKE


WATER ELEV APPROX 930.8 12 SEPT 80

— SHORELINE 1/2/75

PLAN



E 2,016,400



2. THIS PLAN WAS COMPILED FROM RECORD DRAWINGS FOR THE INSTALLATION OF "WATER TRANSMISSION MAIN REINFORCEMENT" BY CAHN ENGINEERS INC DATED AUGUST 1976 AND FROM NOTES ON NEWTON, NJ WATER WORKS CONSTRUCTION AND LITIGATION, BY LL TRIBUS, JUNE 1909

3 LOCATION OF CONCRETE FACING OVER OLD DAM, SHOWN IN SECTION A-A IS ESTIMATED AND MAY VARY

IN 804,800

E 2,016,400

980

960

940

SURFACE  
DAM KEYED  
DCK

920

900

<b>MORRIS LAKE DAM</b>	
<b>NEWTON</b>	<b>NEW JERSEY</b>
<b>DAM PLAN, PROFILE AND SECTION</b>	
<b>LANGAN ENGINEERING ASSOCIATES, INC.</b>	
990 CLIFTON AVE CLIFTON, N. J. 07012	
DRAWN BY: S.A.	SCALE: AS SHOWN FOR THE 00140
CHECKED BY: S.A.	DATE: 04 00% 00 FOR THE 2

**APPENDIX 1**

**HYDROLOGIC AND HYDRAULIC DATA**

**CHECK LIST VISUAL INSPECTION**

**CHECK LIST ENGINEERING DATA**

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 1.07 sq. mi, wooded or forest land, 5.4% avg. slope

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 939.6 ft MSL (approx 2470 ac ft)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 942.8 (approx 2985 ac ft)  
Assumes top of dam

ELEVATION MAXIMUM DESIGN POOL: 942.8 (Assumes top of dam)

ELEVATION TOP DAM: 942.8

CREST: Spillway

- a. Elevation 939.6
- b. Type Broad crested trapazoidal weir
- c. Width 5 ft
- d. Length 14 ft
- e. Location Spillover west abutment
- f. Number and Type of Gates None

OUTLET WORKS: \_\_\_\_\_

- a. Type 16 and 12 inch dia. water supply mains
- b. Location Below gatehouse
- c. Entrance inverts Approx El 920 for both
- d. Exit inverts Approx El 920 for both
- e. Emergency draindown facilities None

HYBROMETEOROLOGICAL GAGES: None observed

- a. Type \_\_\_\_\_
- b. Location \_\_\_\_\_
- c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: 283 cfs @ top of dam



Check List  
Visual Inspection  
Phase 1

Name Dam MORRIS LAKE DAM County SUSSEX State N.J. Coordinators N. J. DEP

Date(s) Inspection 9/12/80  
12/1/80

Weather Clear  
Clear

Temperature Low 70's  
Low 40's

Approx

Pool Elevation at Time of Inspection 936.4 M.S.L. Tailwater at Time of Inspection 930.8 M.S.L.

Inspection Personnel:

R. W. Greene, LEA (9/12/80)

D. Leary, LEA (12/1/80)

V. Urban, LEA (9/12/80)

P. Yu, LEA (12/1/80)

Mr. Harold Beemer, New Water  
Department (9/12/80)

R. W. Greene Recorder

# CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEE PAGE ON LEAKAGE	LIMITED SEEPAGE ON DOWNSTREAM FACE BELOW GATEHOUSE APPROX 10 FT DOWN FROM TOP OF DAM.	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	EAST SIDE-DAM ABUTS TO ROCK OUTCROP - NO SIGNS OF LEAKAGE U/S CONCRETE DETERIORATING AT EAST ABUTMENT. WEST SIDE - DAM ABUTS TO ROCK LEDGE NO SIGN OF LEAKAGE.	REPAIR DETERIORATED CONCRETE.
DRAINS	NONE OBSERVED	
WATER PASSAGES	NO APPARENT DEFECTS OBSERVED.	
FOUNDATION	REPORTED TO BE BEDROCK.	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	NUMEROUS CRACKS AND SPALLING OF CONCRETE (GUNITED) FACING ALONG UPSTREAM & DOWNSTREAM FACE. GRASS GROWING OUT OF MANY CRACKS ON THE DOWNSTREAM FACE.	INVESTIGATE EXTENT OF DETERIORATION. REPAIR IF NECESSARY.
STRUCTURAL CRACKING	NONE OBSERVED.	
VERTICAL AND HORIZONTAL ALIGNMENT	VERTICAL - ARCHED UPSTREAM HORIZONTAL - LEVEL	
MONOLITH JOINTS	SPILLWAY APPEARED TIGHT, NO SIGNS OF LEAKAGE.	
CONSTRUCTION JOINTS	APPEARED TIGHT, NO SIGNS OF LEAKAGE.	

# OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	12 INCH CI AND 16 INCH RCP WATER SUPPLY TO TOWN OF NEWTON EMERGENCY PUMP IN GATE HOUSE WELL	PIPELINES NOT VISIBLE
INTAKE STRUCTURE	CANNOT BE INSPECTED	
OUTLET STRUCTURE	NONE. WATER SUPPLY LINES TO TOWN OF NEWTON.	
OUTLET CHANNEL	ROCK OUTCROP FROM SPILLWAY TO LARGE POND (GLEN LAKE) ADJACENT TO DOWNSTREAM FACE OF DAM.	
EMERGENCY GATE	NONE.	

# UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	NO APPARENT DEFECTS OBSERVED.	
APPROACH CHANNEL	NONE - UNOBSTRUCTED	
DISCHARGE CHANNEL	NATURAL ROCK OUTCROP TO GLEN LAKE IMMEDIATELY DOWNSTREAM OF DAM. BRUSH GROWING IN CHANNEL.	REMOVE BRUSH.
BRIDGE AND PIERS	FOOT PATH STRUCTURE SPANS OVER SPILLWAY TO FORM FOOT BRIDGE. NO APPARENT DEFECTS OBSERVED.	

INSTRUMENTATION		
VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	TOWN OF NEWTON MONUMENTS. NO REFERENCE MARKS FOUND ON MONUMENTS.	
OBSERVATION WELLS	NONE OBSERVED	
WEIRS	FLOW METERS IN GATE HOUSE FOR 16 INCH AND 12 INCH WATER SUPPLY LINES.	
PIEZOMETERS	NONE OBSERVED	
OTHER	POOL LEVELS TAKEN DAILY BY NEWTON WATER DEPT.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	LARGE PRIVATE POND (GLEN LAKE)	
SLOPES	APPROX 2:1 TO 4:1 EAST SIDE APPROX 10:1 WEST SIDE TREES AND LAWNS & ROCK OUTCROPS	
APPROXIMATE NO. OF HOMES AND POPULATION	APPROX 20 HOMES AROUND GLEN LAKE. ALL APPEAR ABOVE DAM ELEVATION. NORTHERN PORTION OF THE TOWN OF SPARTA IS LOCATED APPROX 1 1/2 MILES FROM THE DAM.	

# RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	APPROX 2H: 1 VERTICAL - ROCK OUTCROPS RIPRAP APPEARS EVEN & WELL PLACED AROUND SHORELINE VISIBLE FROM D.M.	
SEDIMENTATION	NONE OBSERVED WITH THE EXCEPTION OF SLIGHT BOTTOM GROWTH.	



CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	NOTES ON NEWTON, N.J. WATER WORKS CONSTRUCTION AND LITIGATION. NEW ENGLAND WATER WORKS ASSOC. VOL 23, No. 2, JUNE 1909 BY LOUIS L. TRIBUS
REGIONAL VICINITY MAP	MORRIS LAKE DAM DAM PLAN, PROFILE AND SECTION  MORRIS LAKE DAM, HIGH STREET RESERVOIR DAM TOWN OF NEWTON, NEWTON, N.J. PHASE I INSPECTION REPORT BY CAHN ENGINEERING, INC., WALLINGFORD, CONN. MARCH 1979.
CONSTRUCTION HISTORY	MORRIS LAKE DAM, HIGH STREET RESERVOIR DAM TOWN OF NEWTON, NEWTON, N.J. PHASE I INSPECTION REPORT BY CAHN ENGINEERING, INC., WALLINGFORD, CONN. MARCH 1979.
TYPICAL SECTIONS OF DAM	MORRIS LAKE DAM DAM PLAN, PROFILE AND SECTION
HYDROLOGIC/HYDRAULIC DATA	
OUTLETS - PLAN	NOTES ON NEWTON, N.J. WATER WORKS CONSTRUCTION AND LITIGATION. NEW ENGLAND WATER WORKS ASSOC., VOL 23, NO. 2, JUNE 1909 BY LOUIS L. TRIBUS
- DETAILS	
-CONSTRAINTS -DISCHARGE RATINGS	
RAINFALL/RESERVOIR RECORDS	
	NONE AVAILABLE

ITEM	REMARKS
DESIGN REPORTS	NONE AVAILABLE
GEOLOGY REPORTS	NONE ABAILABLE
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	NONE AVAILABLE
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	NONE AVAILABLE
POST-CONSTRUCTION SURVEYS OF DAM	MORRIS LAKE DAM DAM PLAN, PROFILE AND SECTION
BORROW SOURCES.	REPORTED TO BE LOCAL ROCK AT DAMSITE.

ITEM REMARKS

MONITORING SYSTEMS FLOW METER ON 12 INCH AND 16 INCH WATER SUPPLY PIPELINES.

MODIFICATIONS RESURFACING, RAISING AND CONSTRUCTION OF GATE HOUSE IN 1927.

NEW 20 INCH WATER INTAKE INSTALLED IN 1929.

16 INCH WATER SUPPLY MAIN INSTALLED IN 1978 THROUGH 24 INCH LOW LEVEL OUTLET.

HIGH POOL RECORDS UNAVAILABLE.

POST CONSTRUCTION ENGINEERING  
STUDIES AND REPORTS MORRIS LAKE DAM, HIGH STREET RESERVOIR DAM  
TOWN OF NEWTON, NEWTON, N. J. PHASE I INSPECTION REPORT BY CAHN  
ENGINEERING, INC., WALLINGFORD, CONN.  
MARCH 1979

PRIOR ACCIDENTS OR FAILURE OF DAM  
DESCRIPTION NONE REPORTED  
REPORTS

MAINTENANCE  
OPERATION RECORDS DAILY FLOW RECORDS OF 12 INCH AND 16 INCH WATER SUPPLY MAINS.

ITEM	REMARKS
SPILLWAY PLAN	MORRIS LAKE DAM, HIGH STREET RESERVOIR DAM
SECTIONS	TOWN OF NEWTON, NEWTON, N.J. PHASE I INSPECTION REPORT BY CAHN ENGINEERING, INC. WALLINGFORD, CONN., MARCH 1979
DETAILS	
OPERATING EQUIPMENT PLANS & DETAILS	MORRIS LAKE DAM, HIGH STREET RESERVOIR DAM TOWN OF NEWTON, NEWTON, N.J. PHASE I INSPECTION REPORT BY CAHN ENGINEERING, INC., WALLINGFORD, CONN., MARCH 1979

**APPENDIX 2**  
**PHOTOGRAPHS**



Downstream face of dam. Looking  
west from east side of dam.

12 September 1980



Downstream wing wall west of  
spillway and discharge channel.

12 September 1980



Upstream face of dam, east side,  
showing east abutment and gate house.

12 September 1980



Upstream face of dam, west side,  
showing spillway opening.

12 September 1980



West shoreline of Reservoir viewed  
from center of dam

12 September 1980



East shoreline of Reservoir viewed  
from center of dam.

12 September 1980



**APPENDIX 3**  
**HYDROLOGIC COMPUTATIONS**

HYDROLOGICAL COMPUTATIONSMORRIS LAKE DAMA. Location: Sussex County, N.J. - Wallkill RiverB. Drainage Area: 1.07 sq. mi (684 acres)C. Lake area: 157 acresD. Classification: size - intermediate  
hazard - highE. Spillway Design Flood: PMFF. PMP

1. Dam located in zone 6 (near zone 1 boundary)

PMP = 22.3 inches (for 200 sq. mi, 24 hr.,  
"all season envelope") \*2. PMF must be adjusted for basin size under  
10 sq. mi: use factor of 80% \*\*

% Factor for $\leq 10$ sq mi			
Duration	Zone 1	Zone 6	Avg
0-6	111	113	112
0-12	123	123	123
0-24	133	132	132
0-48	142	142	142

\* HMR #33

\*\* Page 48 "Design of Small Dams".

BY VAU DATE        Morris Lake DamJOB NO. 80145CKD Dy DATE 7/7/81SHEET NO. 1 OF

G. DETERMINE TIME OF CONCENTRATION

Majority area of watershed is woodland.  
There is no main stream. The watercourse is  
overland flow over poorly defined channel & woodland.



1. Estimate  $T_c$  based on average velocity  
and length —

$$\text{Ave slope}(\%) = \frac{1300 - 950}{6500} \times 100\% \doteq 5.4\%$$

Assume half of the watercourse flow over poorly defined  
channel and half over forest and fallow

From Fig 3-1, SCS TR-55

	Velocity
poorly defined channel	2.5 fps
forest & fallow	0.8 fps

$$T_c = \frac{3250}{2.5 \times 60 \times 60} + \frac{3250}{0.8 \times 60 \times 60} \doteq 1.5 \text{ hrs.}$$

$$L = 0.6 T_c = 0.9 \text{ hrs}$$

2. Estimate  $T_c$  from curve number method

From Table 2-2 SCS TR-55

for soil group C (County Soil Survey - Sussex N.J.)  
wood or forestland  $CN = 74$

$$S = \frac{1000}{CN} - 10 = \frac{1000}{74} - 10 = 3.51$$

$$\begin{aligned} \text{Lag time } L &= \frac{L^{0.8} (S+1)^{0.7}}{1900 (Y)^{0.5}} \quad \text{Eq. 3-2 TR-55} \\ &= \frac{6500^{0.8} (4.51)^{0.7}}{1900 (5.4)^{0.5}} = 0.73 \text{ hr.} \end{aligned}$$

$$\text{Use } \boxed{L = 0.8 \text{ hr.}}$$

BY Py DATE 3/17/81 Morris Lake

JOB NO. 80145

CKD RWG DATE 2/19/81


SHEET NO. 2 OF

ELEVATION	SPILLWAY		DAM		$Q_{CLH}^{3/2}$	$\Sigma Q_{cs}$
	H, ft	C	H, ft	C		
939.6	0	-			0	0
940.0	0.4	2.50			9	9
941.0	1.4	2.65			61	61
941.6	2.0	2.65			105	105
942.0	1.4	0.85			226	226
942.8	2.2	0.85	0	-	283	283
943.0	2.4	0.85	0.2	2.34	33	329
944.0	3.4	0.85	1.2	2.66	560	912
945.0	4.4	0.85	2.2	2.66	1389	1790
946.0	5.4	0.85	3.2	2.67	2445	2889

WEIR FLOW  $Q = CLH^{3/2}$  C VALUES FROM HANDBOOK OF HYDRAULICS TABLE 5-3 PG 5-4  
 ORIFICE FLOW THRU SPILLWAY OCCURS AT EL 941.6<sup>+</sup>,  $Q = CA\sqrt{2gH}$ , C VALUES  
 FROM DESIGN OF SMALL DAMS, TABLE 33, PAGE 472. C=0.85 FOR SQUARE EDGED  
 ENTRANCES.

BY RWG DATE 10/31/80 DISCHARGE SUMMARY  
 CKD TR DATE 2/17/81 MORRIS LAKE DAM

JOB NO. 80145  
 SHEET NO. 3 OF



BY RWG DATE 10/31/80 SPILLWAY RATING CURVE JOB NO. 80145  
 CKD. Py DATE 2/17/81 MORRIS LAKE DAM SHEET NO. 4 OF 4

Reservoir Storage Capacity

Assume a linear distribution for the area of the lake with elevation. Start at a zero storage at the crest of the spillway.

Area of Lake = 157 ac @ 939.6

Length of equivalent square = 2615.13 ft

Take average side slope: 1 V : 10 H

∴ for every foot of water above the crest of the spillway the length of the equivalent square increases by:  $1 \times 2 \times 10 = 20$  ft

	Elevation (ft)	H (ft)	Length of Equiv. Square (ft)	Area of Lake (acres)
SPILLWAY CREST	939.6	0	2615.13	157
	940.0	0.4	2623.13	157.96
	941.0	1.4	2643.13	160.38
	942.0	2.4	2663.13	162.82
TOP of Dam	942.8	3.2	2679.13	164.78
	943.0	3.4	2683.13	165.27
	944.0	4.4	2703.13	167.74
	945.0	5.4	2723.13	170.24
	946.0	6.4	2743.13	172.74

Storage Capacity vs. elevation is calculated by  
HEC 1

BY RWG

DATE 10/31/80

MORRIS LAKE DAM

JOB NO. 80145

CKD, Jm

DATE 4/7/81


SHEET NO. 5 OF

## SUMMARY OF HYDROGRAPH AND FLOOD ROUTING

- 1) HYDROGRAPH & ROUTING CALCULATED USING HEC-1
- 2) PMF for MORRIS LAKE DAM IS 4533 cfs (routed to 1545 cfs)
- 3) Routing of PMF indicates that the dam will overtop by 1.92 ft.
- 4) Routing of THE  $\frac{1}{2}$  PMF INDICATES that the dam can adequately pass the  $\frac{1}{2}$  PMF.

### OVERTOPPING POTENTIAL

- 1) Various % of PMF have been routed using HEC-1 DB
- 2) Plot peak outflow vs % PMF



- 3) Dam overtops at elev. 942.8 with  $Q = 283$  cfs  
 $\therefore$  dam can pass approx. 50 % of PMF

BY <u>RWG</u>	DATE <u>11/3/80</u>	<u>HEC-1 SUMMARY</u>	JOB NO. <u>80145</u>
CKD <u>py</u>	DATE <u>7/1/81</u>		SHEET NO. <u>6</u> OF <u>    </u>

HEC-1 OUTPUT  
MORRIS LAKE DAM



MORRIS LAKE DAM (00306)  
INFLOW HYDROGRAPHY AND ROUTING  
N.J. DAM INSPECTION

1A1  
A2  
A3  
B  
B1  
B2  
B3  
B4  
B5  
B6  
B7  
B8  
B9  
B10  
B11  
B12  
B13  
B14  
B15  
B16  
B17  
B18  
B19  
B20  
B21  
B22  
B23  
B24  
B25  
B26  
B27  
B28  
B29  
B30  
B31  
B32  
B33  
B34  
B35  
B36  
B37  
B38  
B39  
B40  
B41  
B42  
B43  
B44  
B45  
B46  
B47  
B48  
B49  
B50  
B51  
B52  
B53  
B54  
B55  
B56  
B57  
B58  
B59  
B60  
B61  
B62  
B63  
B64  
B65  
B66  
B67  
B68  
B69  
B70  
B71  
B72  
B73  
B74  
B75  
B76  
B77  
B78  
B79  
B80  
B81  
B82  
B83  
B84  
B85  
B86  
B87  
B88  
B89  
B90  
B91  
B92  
B93  
B94  
B95  
B96  
B97  
B98  
B99  
C  
C1  
C2  
C3  
C4  
C5  
C6  
C7  
C8  
C9  
C10  
C11  
C12  
C13  
C14  
C15  
C16  
C17  
C18  
C19  
C20  
C21  
C22  
C23  
C24  
C25  
C26  
C27  
C28  
C29  
C30  
C31  
C32  
C33  
C34  
C35  
C36  
C37  
C38  
C39  
C40  
C41  
C42  
C43  
C44  
C45  
C46  
C47  
C48  
C49  
C50  
C51  
C52  
C53  
C54  
C55  
C56  
C57  
C58  
C59  
C60  
C61  
C62  
C63  
C64  
C65  
C66  
C67  
C68  
C69  
C70  
C71  
C72  
C73  
C74  
C75  
C76  
C77  
C78  
C79  
C80  
C81  
C82  
C83  
C84  
C85  
C86  
C87  
C88  
C89  
C90  
C91  
C92  
C93  
C94  
C95  
C96  
C97  
C98  
C99  
D  
D1  
D2  
D3  
D4  
D5  
D6  
D7  
D8  
D9  
D10  
D11  
D12  
D13  
D14  
D15  
D16  
D17  
D18  
D19  
D20  
D21  
D22  
D23  
D24  
D25  
D26  
D27  
D28  
D29  
D30  
D31  
D32  
D33  
D34  
D35  
D36  
D37  
D38  
D39  
D40  
D41  
D42  
D43  
D44  
D45  
D46  
D47  
D48  
D49  
D50  
D51  
D52  
D53  
D54  
D55  
D56  
D57  
D58  
D59  
D60  
D61  
D62  
D63  
D64  
D65  
D66  
D67  
D68  
D69  
D70  
D71  
D72  
D73  
D74  
D75  
D76  
D77  
D78  
D79  
D80  
D81  
D82  
D83  
D84  
D85  
D86  
D87  
D88  
D89  
D90  
D91  
D92  
D93  
D94  
D95  
D96  
D97  
D98  
D99  
E  
E1  
E2  
E3  
E4  
E5  
E6  
E7  
E8  
E9  
E10  
E11  
E12  
E13  
E14  
E15  
E16  
E17  
E18  
E19  
E20  
E21  
E22  
E23  
E24  
E25  
E26  
E27  
E28  
E29  
E30  
E31  
E32  
E33  
E34  
E35  
E36  
E37  
E38  
E39  
E40  
E41  
E42  
E43  
E44  
E45  
E46  
E47  
E48  
E49  
E50  
E51  
E52  
E53  
E54  
E55  
E56  
E57  
E58  
E59  
E60  
E61  
E62  
E63  
E64  
E65  
E66  
E67  
E68  
E69  
E70  
E71  
E72  
E73  
E74  
E75  
E76  
E77  
E78  
E79  
E80  
E81  
E82  
E83  
E84  
E85  
E86  
E87  
E88  
E89  
E90  
E91  
E92  
E93  
E94  
E95  
E96  
E97  
E98  
E99  
F  
F1  
F2  
F3  
F4  
F5  
F6  
F7  
F8  
F9  
F10  
F11  
F12  
F13  
F14  
F15  
F16  
F17  
F18  
F19  
F20  
F21  
F22  
F23  
F24  
F25  
F26  
F27  
F28  
F29  
F30  
F31  
F32  
F33  
F34  
F35  
F36  
F37  
F38  
F39  
F40  
F41  
F42  
F43  
F44  
F45  
F46  
F47  
F48  
F49  
F50  
F51  
F52  
F53  
F54  
F55  
F56  
F57  
F58  
F59  
F60  
F61  
F62  
F63  
F64  
F65  
F66  
F67  
F68  
F69  
F70  
F71  
F72  
F73  
F74  
F75  
F76  
F77  
F78  
F79  
F80  
F81  
F82  
F83  
F84  
F85  
F86  
F87  
F88  
F89  
F90  
F91  
F92  
F93  
F94  
F95  
F96  
F97  
F98  
F99  
G  
G1  
G2  
G3  
G4  
G5  
G6  
G7  
G8  
G9  
G10  
G11  
G12  
G13  
G14  
G15  
G16  
G17  
G18  
G19  
G20  
G21  
G22  
G23  
G24  
G25  
G26  
G27  
G28  
G29  
G30  
G31  
G32  
G33  
G34  
G35  
G36  
G37  
G38  
G39  
G40  
G41  
G42  
G43  
G44  
G45  
G46  
G47  
G48  
G49  
G50  
G51  
G52  
G53  
G54  
G55  
G56  
G57  
G58  
G59  
G60  
G61  
G62  
G63  
G64  
G65  
G66  
G67  
G68  
G69  
G70  
G71  
G72  
G73  
G74  
G75  
G76  
G77  
G78  
G79  
G80  
G81  
G82  
G83  
G84  
G85  
G86  
G87  
G88  
G89  
G90  
G91  
G92  
G93  
G94  
G95  
G96  
G97  
G98  
G99  
H  
H1  
H2  
H3  
H4  
H5  
H6  
H7  
H8  
H9  
H10  
H11  
H12  
H13  
H14  
H15  
H16  
H17  
H18  
H19  
H20  
H21  
H22  
H23  
H24  
H25  
H26  
H27  
H28  
H29  
H30  
H31  
H32  
H33  
H34  
H35  
H36  
H37  
H38  
H39  
H40  
H41  
H42  
H43  
H44  
H45  
H46  
H47  
H48  
H49  
H50  
H51  
H52  
H53  
H54  
H55  
H56  
H57  
H58  
H59  
H60  
H61  
H62  
H63  
H64  
H65  
H66  
H67  
H68  
H69  
H70  
H71  
H72  
H73  
H74  
H75  
H76  
H77  
H78  
H79  
H80  
H81  
H82  
H83  
H84  
H85  
H86  
H87  
H88  
H89  
H90  
H91  
H92  
H93  
H94  
H95  
H96  
H97  
H98  
H99  
I  
I1  
I2  
I3  
I4  
I5  
I6  
I7  
I8  
I9  
I10  
I11  
I12  
I13  
I14  
I15  
I16  
I17  
I18  
I19  
I20  
I21  
I22  
I23  
I24  
I25  
I26  
I27  
I28  
I29  
I30  
I31  
I32  
I33  
I34  
I35  
I36  
I37  
I38  
I39  
I40  
I41  
I42  
I43  
I44  
I45  
I46  
I47  
I48  
I49  
I50  
I51  
I52  
I53  
I54  
I55  
I56  
I57  
I58  
I59  
I60  
I61  
I62  
I63  
I64  
I65  
I66  
I67  
I68  
I69  
I70  
I71  
I72  
I73  
I74  
I75  
I76  
I77  
I78  
I79  
I80  
I81  
I82  
I83  
I84  
I85  
I86  
I87  
I88  
I89  
I90  
I91  
I92  
I93  
I94  
I95  
I96  
I97  
I98  
I99  
J  
J1  
J2  
J3  
J4  
J5  
J6  
J7  
J8  
J9  
J10  
J11  
J12  
J13  
J14  
J15  
J16  
J17  
J18  
J19  
J20  
J21  
J22  
J23  
J24  
J25  
J26  
J27  
J28  
J29  
J30  
J31  
J32  
J33  
J34  
J35  
J36  
J37  
J38  
J39  
J40  
J41  
J42  
J43  
J44  
J45  
J46  
J47  
J48  
J49  
J50  
J51  
J52  
J53  
J54  
J55  
J56  
J57  
J58  
J59  
J60  
J61  
J62  
J63  
J64  
J65  
J66  
J67  
J68  
J69  
J70  
J71  
J72  
J73  
J74  
J75  
J76  
J77  
J78  
J79  
J80  
J81  
J82  
J83  
J84  
J85  
J86  
J87  
J88  
J89  
J90  
J91  
J92  
J93  
J94  
J95  
J96  
J97  
J98  
J99  
K  
K1  
K2  
K3  
K4  
K5  
K6  
K7  
K8  
K9  
K10  
K11  
K12  
K13  
K14  
K15  
K16  
K17  
K18  
K19  
K20  
K21  
K22  
K23  
K24  
K25  
K26  
K27  
K28  
K29  
K30  
K31  
K32  
K33  
K34  
K35  
K36  
K37  
K38  
K39  
K40  
K41  
K42  
K43  
K44  
K45  
K46  
K47  
K48  
K49  
K50  
K51  
K52  
K53  
K54  
K55  
K56  
K57  
K58  
K59  
K60  
K61  
K62  
K63  
K64  
K65  
K66  
K67  
K68  
K69  
K70  
K71  
K72  
K73  
K74  
K75  
K76  
K77  
K78  
K79  
K80  
K81  
K82  
K83  
K84  
K85  
K86  
K87  
K88  
K89  
K90  
K91  
K92  
K93  
K94  
K95  
K96  
K97  
K98  
K99  
L  
L1  
L2  
L3  
L4  
L5  
L6  
L7  
L8  
L9  
L10  
L11  
L12  
L13  
L14  
L15  
L16  
L17  
L18  
L19  
L20  
L21  
L22  
L23  
L24  
L25  
L26  
L27  
L28  
L29  
L30  
L31  
L32  
L33  
L34  
L35  
L36  
L37  
L38  
L39  
L40  
L41  
L42  
L43  
L44  
L45  
L46  
L47  
L48  
L49  
L50  
L51  
L52  
L53  
L54  
L55  
L56  
L57  
L58  
L59  
L60  
L61  
L62  
L63  
L64  
L65  
L66  
L67  
L68  
L69  
L70  
L71  
L72  
L73  
L74  
L75  
L76  
L77  
L78  
L79  
L80  
L81  
L82  
L83  
L84  
L85  
L86  
L87  
L88  
L89  
L90  
L91  
L92  
L93  
L94  
L95  
L96  
L97  
L98  
L99  
M  
M1  
M2  
M3  
M4  
M5  
M6  
M7  
M8  
M9  
M10  
M11  
M12  
M13  
M14  
M15  
M16  
M17  
M18  
M19  
M20  
M21  
M22  
M23  
M24  
M25  
M26  
M27  
M28  
M29  
M30  
M31  
M32  
M33  
M34  
M35  
M36  
M37  
M38  
M39  
M40  
M41  
M42  
M43  
M44  
M45  
M46  
M47  
M48  
M49  
M50  
M51  
M52  
M53  
M54  
M55  
M56  
M57  
M58  
M59  
M60  
M61  
M62  
M63  
M64  
M65  
M66  
M67  
M68  
M69  
M70  
M71  
M72  
M73  
M74  
M75  
M76  
M77  
M78  
M79  
M80  
M81  
M82  
M83  
M84  
M85  
M86  
M87  
M88  
M89  
M90  
M91  
M92  
M93  
M94  
M95  
M96  
M97  
M98  
M99  
N  
N1  
N2  
N3  
N4  
N5  
N6  
N7  
N8  
N9  
N10  
N11  
N12  
N13  
N14  
N15  
N16  
N17  
N18  
N19  
N20  
N21  
N22  
N23  
N24  
N25  
N26  
N27  
N28  
N29  
N30  
N31  
N32  
N33  
N34  
N35  
N36  
N37  
N38  
N39  
N40  
N41  
N42  
N43  
N44  
N45  
N46  
N47  
N48  
N49  
N50  
N51  
N52  
N53  
N54  
N55  
N56  
N57  
N58  
N59  
N60  
N61  
N62  
N63  
N64  
N65  
N66  
N67  
N68  
N69  
N70  
N71  
N72  
N73  
N74  
N75  
N76  
N77  
N78  
N79  
N80  
N81  
N82  
N83  
N84  
N85  
N86  
N87  
N88  
N89  
N90  
N91  
N92  
N93  
N94  
N95  
N96  
N97  
N98  
N99  
O  
O1  
O2  
O3  
O4  
O5  
O6  
O7  
O8  
O9  
O10  
O11  
O12  
O13  
O14  
O15  
O16  
O17  
O18  
O19  
O20  
O21  
O22  
O23  
O24  
O25  
O26  
O27  
O28  
O29  
O30  
O31  
O32  
O33  
O34  
O35  
O36  
O37  
O38  
O39  
O40  
O41  
O42  
O43  
O44  
O45  
O46  
O47  
O48  
O49  
O50  
O51  
O52  
O53  
O54  
O55  
O56  
O57  
O58  
O59  
O60  
O61  
O62  
O63  
O64  
O65  
O66  
O67  
O68  
O69  
O70  
O71  
O72  
O73  
O74  
O75  
O76  
O77  
O78  
O79  
O80  
O81  
O82  
O83  
O84  
O85  
O86  
O87  
O88  
O89  
O90  
O91  
O92  
O93  
O94  
O95  
O96  
O97  
O98  
O99  
P  
P1  
P2  
P3  
P4  
P5  
P6  
P7  
P8  
P9  
P10  
P11  
P12  
P13  
P14  
P15  
P16  
P17  
P18  
P19  
P20  
P21  
P22  
P23  
P24  
P25  
P26  
P27  
P28  
P29  
P30  
P31  
P32  
P33  
P34  
P35  
P36  
P37  
P38  
P39  
P40  
P41  
P42  
P43  
P44  
P45  
P46  
P47  
P48  
P49  
P50  
P51  
P52  
P53  
P54  
P55  
P56  
P57  
P58  
P59  
P60  
P61  
P62  
P63  
P64  
P65  
P66  
P67  
P68  
P69  
P70  
P71  
P72  
P73  
P74  
P75  
P76  
P77  
P78  
P79  
P80  
P81  
P82  
P83  
P84  
P85  
P86  
P87  
P88  
P89  
P90  
P91  
P92  
P93  
P94  
P95  
P96  
P97  
P98  
P99  
Q  
Q1  
Q2  
Q3  
Q4  
Q5  
Q6  
Q7  
Q8  
Q9  
Q10  
Q11  
Q12  
Q13  
Q14  
Q15  
Q16  
Q17  
Q18  
Q19  
Q20  
Q21  
Q22  
Q23  
Q24  
Q25  
Q26  
Q27  
Q28  
Q29  
Q30  
Q31  
Q32  
Q33  
Q34  
Q35  
Q36  
Q37  
Q38  
Q39  
Q40  
Q41  
Q42  
Q43  
Q44  
Q45  
Q46  
Q47  
Q48  
Q49  
Q50  
Q51  
Q52  
Q53  
Q54  
Q55  
Q56  
Q57  
Q58  
Q59  
Q60  
Q61  
Q62  
Q63  
Q64  
Q65  
Q66  
Q67  
Q68  
Q69  
Q70  
Q71  
Q72  
Q73  
Q74  
Q75  
Q76  
Q77  
Q78  
Q79  
Q80  
Q81  
Q82  
Q83  
Q84  
Q85  
Q86  
Q87  
Q88  
Q89  
Q90  
Q91  
Q92  
Q93  
Q94  
Q95  
Q96  
Q97  
Q98  
Q99  
R  
R1  
R2  
R3  
R4  
R5  
R6  
R7  
R8  
R9  
R10  
R11  
R12  
R13  
R14  
R15  
R16  
R17  
R18  
R19  
R20  
R21  
R22  
R23  
R24  
R25  
R26  
R27  
R28  
R29  
R30  
R31  
R32  
R33  
R34  
R35  
R36  
R37  
R38  
R39  
R40  
R41  
R42  
R43  
R44  
R45  
R46  
R47  
R48  
R49  
R50  
R51  
R52  
R53  
R54  
R55  
R56  
R57  
R58  
R59  
R60  
R61  
R62  
R63  
R64  
R65  
R66  
R67  
R68  
R69  
R70  
R71  
R72  
R73  
R74  
R75  
R76  
R77  
R78  
R79  
R80  
R81  
R82  
R83  
R84  
R85  
R86  
R87  
R88  
R89  
R90  
R91  
R92  
R93  
R94  
R95  
R96  
R97  
R98  
R99  
S  
S1  
S2  
S3  
S4  
S5  
S6  
S7  
S8  
S9  
S10  
S11  
S12  
S13  
S14  
S15  
S16  
S17  
S18  
S19  
S20  
S21  
S22  
S23  
S24  
S25  
S26  
S27  
S28  
S29  
S30  
S31  
S32  
S33  
S34  
S35  
S36  
S37  
S38  
S39  
S40  
S41  
S42  
S43  
S44  
S45  
S46  
S47  
S48  
S49  
S50  
S51  
S52  
S53  
S54  
S55  
S56  
S57  
S58  
S59  
S60  
S61  
S62  
S63  
S64  
S65  
S66  
S67  
S68  
S69  
S70  
S71  
S72  
S73  
S74  
S75  
S76  
S77  
S78  
S79  
S80  
S81  
S82  
S83  
S84  
S85  
S86  
S87  
S88  
S89  
S90  
S91  
S92  
S93  
S94  
S95  
S96  
S97  
S98  
S99  
T  
T1  
T2  
T3  
T4  
T5  
T6  
T7  
T8  
T9  
T10  
T11  
T12  
T13  
T14  
T15  
T16  
T17  
T18  
T19  
T20  
T21  
T22  
T23  
T24  
T25  
T26  
T27  
T28  
T29  
T30  
T31  
T32  
T33  
T34  
T35  
T36  
T37  
T38  
T39  
T40  
T41  
T42  
T43  
T44  
T45  
T46  
T47  
T48  
T49  
T50  
T51  
T52  
T53  
T54  
T55  
T56  
T57  
T58  
T59  
T60  
T61  
T62  
T63  
T64  
T65  
T66  
T67  
T68  
T69  
T70  
T71  
T72  
T73  
T74  
T75  
T76  
T77  
T78  
T79  
T80  
T81  
T82  
T83  
T84  
T85  
T86  
T87  
T88  
T89  
T90  
T91  
T92  
T93  
T94  
T95  
T96  
T97  
T98  
T99  
U  
U1  
U2  
U3  
U4  
U5  
U6  
U7  
U8  
U9  
U10  
U11  
U12  
U13  
U14  
U15  
U16  
U17  
U18  
U19  
U20  
U21  
U22  
U23  
U24  
U25  
U26  
U27  
U28  
U29  
U30  
U31  
U32  
U33  
U34  
U35  
U36  
U37  
U38  
U39  
U40  
U41  
U42  
U43  
U44  
U45  
U46  
U47  
U48  
U49  
U50  
U51  
U52  
U53  
U54  
U55  
U56  
U57  
U58  
U59  
U60  
U61  
U62  
U63  
U64  
U65  
U66  
U67  
U68  
U69  
U70  
U71  
U72  
U73  
U74  
U75  
U76  
U77  
U78  
U79  
U80  
U81  
U82  
U83  
U84  
U85  
U86  
U87  
U88  
U89  
U90  
U91  
U92  
U93  
U94  
U95  
U96  
U97  
U98  
U99  
V  
V1  
V2  
V3  
V4  
V5  
V6  
V7  
V8  
V9  
V10  
V11  
V12  
V13  
V14  
V15  
V16  
V17  
V18  
V19  
V20  
V21  
V22  
V23  
V24  
V25  
V26  
V27  
V28  
V29  
V30  
V31  
V32  
V33  
V34  
V35  
V36  
V37  
V38  
V39  
V40  
V41  
V42  
V43  
V44  
V45  
V46  
V47  
V48  
V49  
V50  
V51  
V52  
V53  
V54  
V55  
V56  
V57  
V58  
V59  
V60  
V61  
V62  
V63  
V64  
V65  
V66  
V67  
V68  
V69  
V70  
V71  
V72  
V73  
V74  
V75  
V76  
V77  
V78  
V79  
V80  
V81  
V82  
V83  
V84  
V85  
V86  
V87  
V88  
V89  
V90  
V91  
V92  
V93  
V94  
V95  
V96  
V97  
V98  
V99  
W  
W1  
W2  
W3  
W4  
W5  
W6  
W7  
W8  
W9  
W10  
W11  
W12  
W13  
W14  
W15  
W16  
W17  
W18  
W19  
W20  
W21  
W22  
W23  
W24  
W25  
W26  
W27  
W28  
W29  
W30  
W31  
W32  
W33  
W34  
W35  
W36  
W37  
W38  
W39  
W40  
W41  
W42  
W43  
W44  
W45  
W46  
W47  
W48  
W49  
W50  
W51  
W52  
W53  
W54  
W55  
W56  
W57  
W58  
W59  
W60  
W61  
W62  
W63  
W64  
W65  
W66  
W67  
W68  
W69  
W70  
W71  
W72  
W73  
W74  
W75  
W76  
W77  
W78  
W79  
W80  
W81  
W82  
W83  
W84  
W85  
W86  
W87  
W88  
W89  
W90  
W91  
W92  
W93  
W94  
W95  
W96  
W97  
W98  
W99  
X  
X1  
X2  
X3  
X4  
X5  
X6  
X7  
X8  
X9  
X10  
X11  
X12  
X13  
X14  
X15  
X16  
X17  
X18  
X19  
X20  
X21  
X22  
X23  
X24  
X25  
X26  
X27  
X28  
X29  
X30  
X31  
X32  
X33  
X34  
X35  
X36  
X37  
X38  
X39  
X40  
X41  
X42  
X43  
X44  
X45  
X46  
X47  
X48  
X49  
X50  
X51  
X52  
X53  
X54  
X55  
X56  
X57  
X58  
X59  
X60  
X61  
X62  
X63  
X64  
X65  
X66  
X67  
X68  
X69  
X70  
X71  
X72  
X73  
X74  
X75  
X76  
X77  
X78  
X79  
X80  
X81  
X82  
X83  
X84  
X85  
X86  
X87  
X88  
X89  
X90  
X91  
X92  
X93  
X94  
X95  
X96  
X97  
X98  
X99  
Y  
Y1  
Y2  
Y3  
Y4  
Y5  
Y6  
Y7  
Y8  
Y9  
Y10  
Y11  
Y12  
Y13  
Y14  
Y15  
Y16  
Y17  
Y18  
Y19  
Y20  
Y21  
Y22  
Y23  
Y24  
Y25  
Y26  
Y27  
Y28  
Y29  
Y30  
Y31  
Y32  
Y33  
Y34  
Y35  
Y36  
Y37  
Y38  
Y39  
Y40  
Y41  
Y42  
Y43  
Y44  
Y45  
Y46  
Y47  
Y48  
Y49  
Y50  
Y51  
Y52  
Y53  
Y54  
Y55  
Y56  
Y57  
Y58  
Y59  
Y60  
Y61  
Y62  
Y63  
Y64  
Y65  
Y66  
Y67  
Y68  
Y69  
Y70  
Y71  
Y72  
Y73  
Y74  
Y75  
Y76  
Y77  
Y78  
Y79  
Y80  
Y81  
Y82  
Y83  
Y84  
Y85  
Y86  
Y87  
Y88  
Y89  
Y90  
Y91  
Y92  
Y93  
Y94  
Y95  
Y96  
Y97  
Y98  
Y99  
Z  
Z1  
Z2  
Z3  
Z4  
Z5  
Z6  
Z7  
Z8  
Z9  
Z10  
Z11  
Z12  
Z13  
Z14  
Z15  
Z16  
Z17  
Z18  
Z19  
Z20  
Z21  
Z22  
Z23  
Z24  
Z25  
Z26  
Z27  
Z28  
Z29  
Z30  
Z31  
Z32  
Z33  
Z34  
Z35  
Z36  
Z37  
Z38  
Z39  
Z40  
Z41  
Z42  
Z43  
Z44  
Z45  
Z46  
Z47  
Z48  
Z49  
Z50  
Z51  
Z52  
Z53  
Z54  
Z55  
Z56  
Z57  
Z58  
Z59  
Z60  
Z61  
Z62  
Z63  
Z64  
Z65  
Z66  
Z67  
Z68  
Z69  
Z70  
Z71  
Z72  
Z73  
Z74  
Z75  
Z76  
Z77  
Z78  
Z79  
Z80  
Z81  
Z82  
Z83  
Z84  
Z85  
Z86  
Z87  
Z88  
Z89  
Z90  
Z91  
Z92  
Z93  
Z94  
Z95  
Z96  
Z97  
Z98  
Z99

290
-----

FLOOD HYDROGRAPH PACKAGE (HEC-1)

\*\*\*\*\*  
LAST MODIFICATION 26 FEB 79  
\*\*\*\*\*

RUN DATE 81/02/18.  
TIME 10.22.02.

MORRIS LAKE DAM (00306)  
INFLOW HYDROGRAPH AND ROUTING  
N.J. DAM INSPECTION

NO NHR NHIN IDAY IHR IMIN METRC IFLT IPRY NSIAN  
290 0 10 0 0 0 0 0 0  
JOPER NWT LROPT TRACE  
3 0 0 0

JOB SPECIFICATION

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

COMPUTE HYDROGRAPH

ISTAQ ICOMP IECON ITAFE JFLT JPRY INAME ISAGE IAUTO  
1 0 0 0 0 0 1 0 0

INHYDQ IUNG TAKEA SNAP TRSDA TRSFC RATIO ISNOW ISAME LOCAL  
1 2 1.07 0.00 1.07 .80 0.000 0 0 0

HYDROGRAPH DATA

PRECIP DATA  
SPFE FMS R6 R12 R24 R48 R72 R96  
0.00 22.30 112.00 123.00 132.00 142.00 0.00 0.00

LOSS DATA

LROPT STKR ULTKR RTIOL ERAIN STKRS RTIOL STRTL CNSTL ALSMX RTIMP  
0 0.00 0.00 1.00 0.00 0.00 1.00 1.00 .15 0.00 0.00

UNIT HYDROGRAPH DATA  
TC= 0.00 LAG= .80

RECESSION DATA  
STRTO= -2.00 GRCSN= 0.00 RTIUR= 1.00

UNIT HYDROGRAPH 26 END OF PERIOD ORIGINATES, IC= 0.00 HOURS, LAG= .80 VOL= 1.00  
54. 166. 349. 515. 582. 568. 494. 391. 270. 198.  
148. 80. 59. 43. 31. 23. 17. 13. 9.  
7. 5. 4. 3. 2. 1.

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP
1.01	.10	1	.00	0.00	.00	2.	1.02	.20	146	.02	0.00	.02	2.
1.01	.20	2	.00	0.00	.00	2.	1.02	.30	147	.02	0.00	.02	2.
1.01	.30	3	.00	0.00	.00	2.	1.02	.40	148	.02	0.00	.02	2.
1.01	.40	4	.00	0.00	.00	2.	1.02	.50	149	.02	0.00	.02	2.
1.01	.50	5	.00	0.00	.00	2.	1.02	1.00	150	.02	0.00	.02	2.
1.01	1.00	6	.00	0.00	.00	2.	1.02	1.10	151	.02	0.00	.02	2.
1.01	1.10	7	.00	0.00	.00	2.	1.02	1.20	152	.02	0.00	.02	2.
1.01	1.20	8	.00	0.00	.00	2.	1.02	1.30	153	.02	0.00	.02	2.
1.01	1.30	9	.00	0.00	.00	2.	1.02	1.40	154	.02	0.00	.02	2.
1.01	1.40	10	.00	0.00	.00	2.	1.02	1.50	155	.02	0.00	.02	2.

1.01	2.00	1.00	0.00	1.00	1.02	1.10	157	1.02	0.00	0.02	1.2
1.01	2.10	1.00	0.00	1.00	1.02	2.20	158	0.02	0.00	0.02	2.
1.01	2.20	1.00	0.00	1.00	1.02	2.30	159	0.02	0.00	0.02	2.
1.01	2.30	1.00	0.00	1.00	1.02	2.40	160	0.02	0.00	0.02	2.
1.01	2.40	1.00	0.00	1.00	1.02	2.50	161	0.02	0.00	0.02	2.
1.01	2.50	1.00	0.00	1.00	1.02	3.00	162	0.02	0.00	0.02	2.
1.01	3.00	1.00	0.00	1.00	1.02	3.10	163	0.02	0.00	0.02	2.
1.01	3.10	1.00	0.00	1.00	1.02	3.20	164	0.02	0.00	0.02	2.
1.01	3.20	1.00	0.00	1.00	1.02	3.30	165	0.02	0.00	0.02	2.
1.01	3.30	1.00	0.00	1.00	1.02	3.40	166	0.02	0.00	0.02	2.
1.01	3.40	1.00	0.00	1.00	1.02	3.50	167	0.02	0.00	0.02	2.
1.01	3.50	1.00	0.00	1.00	1.02	4.00	168	0.02	0.00	0.02	2.
1.01	4.00	1.00	0.00	1.00	1.02	4.10	169	0.02	0.00	0.02	2.
1.01	4.10	1.00	0.00	1.00	1.02	4.20	170	0.02	0.00	0.02	2.
1.01	4.20	1.00	0.00	1.00	1.02	4.30	171	0.02	0.00	0.02	2.
1.01	4.30	1.00	0.00	1.00	1.02	4.40	172	0.02	0.00	0.02	2.
1.01	4.40	1.00	0.00	1.00	1.02	4.50	173	0.02	0.00	0.02	2.
1.01	4.50	1.00	0.00	1.00	1.02	5.00	174	0.02	0.00	0.02	2.
1.01	5.00	1.00	0.00	1.00	1.02	5.10	175	0.02	0.00	0.02	2.
1.01	5.10	1.00	0.00	1.00	1.02	5.20	176	0.02	0.00	0.02	2.
1.01	5.20	1.00	0.00	1.00	1.02	5.30	177	0.02	0.00	0.02	2.
1.01	5.30	1.00	0.00	1.00	1.02	5.40	178	0.02	0.00	0.02	2.
1.01	5.40	1.00	0.00	1.00	1.02	5.50	179	0.02	0.00	0.02	2.
1.01	5.50	1.00	0.00	1.00	1.02	6.00	180	0.02	0.00	0.02	2.
1.01	6.00	1.00	0.00	1.00	1.02	6.10	181	0.03	0.03	0.03	4.
1.01	6.10	1.00	0.00	1.00	1.02	6.20	182	0.03	0.03	0.03	9.
1.01	6.20	1.00	0.00	1.00	1.02	6.30	183	0.03	0.03	0.03	19.
1.01	6.30	1.00	0.00	1.00	1.02	6.40	184	0.03	0.03	0.03	34.
1.01	6.40	1.00	0.00	1.00	1.02	6.50	185	0.03	0.03	0.03	51.
1.01	6.50	1.00	0.00	1.00	1.02	7.00	186	0.03	0.03	0.03	68.
1.01	7.00	1.00	0.00	1.00	1.02	7.10	187	0.03	0.03	0.03	83.
1.01	7.10	1.00	0.00	1.00	1.02	7.20	188	0.03	0.03	0.03	94.
1.01	7.20	1.00	0.00	1.00	1.02	7.30	189	0.03	0.03	0.03	103.
1.01	7.30	1.00	0.00	1.00	1.02	7.40	190	0.03	0.03	0.03	108.
1.01	7.40	1.00	0.00	1.00	1.02	7.50	191	0.03	0.03	0.03	112.
1.01	7.50	1.00	0.00	1.00	1.02	8.00	192	0.03	0.03	0.03	116.
1.01	8.00	1.00	0.00	1.00	1.02	8.10	193	0.03	0.03	0.03	118.
1.01	8.10	1.00	0.00	1.00	1.02	8.20	194	0.03	0.03	0.03	120.
1.01	8.20	1.00	0.00	1.00	1.02	8.30	195	0.03	0.03	0.03	121.
1.01	8.30	1.00	0.00	1.00	1.02	8.40	196	0.03	0.03	0.03	122.
1.01	8.40	1.00	0.00	1.00	1.02	8.50	197	0.03	0.03	0.03	123.
1.01	8.50	1.00	0.00	1.00	1.02	9.00	198	0.03	0.03	0.03	123.
1.01	9.00	1.00	0.00	1.00	1.02	9.10	199	0.03	0.03	0.03	123.
1.01	9.10	1.00	0.00	1.00	1.02	9.20	200	0.03	0.03	0.03	124.
1.01	9.20	1.00	0.00	1.00	1.02	9.30	201	0.03	0.03	0.03	124.
1.01	9.30	1.00	0.00	1.00	1.02	9.40	202	0.03	0.03	0.03	124.
1.01	9.40	1.00	0.00	1.00	1.02	9.50	203	0.03	0.03	0.03	124.
1.01	9.50	1.00	0.00	1.00	1.02	10.00	204	0.03	0.03	0.03	124.
1.01	10.00	1.00	0.00	1.00	1.02	10.10	205	0.03	0.03	0.03	124.
1.01	10.10	1.00	0.00	1.00	1.02	10.20	206	0.03	0.03	0.03	124.
1.01	10.20	1.00	0.00	1.00	1.02	10.30	207	0.03	0.03	0.03	124.
1.01	10.30	1.00	0.00	1.00	1.02	10.40	208	0.03	0.03	0.03	124.
1.01	10.40	1.00	0.00	1.00	1.02	10.50	209	0.03	0.03	0.03	124.
1.01	10.50	1.00	0.00	1.00	1.02	11.00	210	0.03	0.03	0.03	124.
1.01	11.00	1.00	0.00	1.00	1.02	11.10	211	0.03	0.03	0.03	124.
1.01	11.10	1.00	0.00	1.00	1.02	11.20	212	0.03	0.03	0.03	124.
1.01	11.20	1.00	0.00	1.00	1.02	11.30	213	0.03	0.03	0.03	124.
1.01	11.30	1.00	0.00	1.00	1.02	11.40	214	0.03	0.03	0.03	124.
1.01	11.40	1.00	0.00	1.00	1.02	11.50	215	0.03	0.03	0.03	124.
1.01	11.50	1.00	0.00	1.00	1.02	12.00	216	0.03	0.03	0.03	124.
1.01	12.00	1.00	0.00	1.00	1.02	12.10	217	0.03	0.03	0.03	139.
1.01	12.10	1.00	0.00	1.00	1.02	12.20	218	0.03	0.03	0.03	183.
1.01	12.20	1.00	0.00	1.00	1.02	12.30	219	0.03	0.03	0.03	283.
1.01	12.30	1.00	0.00	1.00	1.02	12.40	220	0.03	0.03	0.03	428.
1.01	12.40	1.00	0.00	1.00	1.02	12.50	221	0.03	0.03	0.03	588.

1.01	13.00	.03	0.00	.03	1.02	13.10	223	.40	.37	.03	887.
1.01	13.10	.03	0.00	.03	1.02	13.20	224	.40	.37	.03	1007.
1.01	13.20	.03	0.00	.03	1.02	13.30	225	.40	.37	.03	1106.
1.01	13.30	.03	0.00	.03	1.02	13.40	226	.40	.37	.03	1193.
1.01	13.40	.03	0.00	.03	1.02	13.50	227	.40	.37	.03	1275.
1.01	13.50	.03	0.00	.03	1.02	14.00	228	.40	.37	.03	1344.
1.01	14.00	.03	0.00	.03	1.02	14.10	229	.50	.47	.03	1404.
1.01	14.10	.04	0.00	.04	1.02	14.20	230	.50	.47	.03	1463.
1.01	14.20	.04	0.00	.04	1.02	14.30	231	.50	.47	.03	1528.
1.01	14.30	.04	0.00	.04	1.02	14.40	232	.50	.47	.03	1601.
1.01	14.40	.04	0.00	.04	1.02	14.50	233	.50	.47	.03	1676.
1.01	14.50	.04	0.00	.04	1.02	15.00	234	.50	.47	.03	1745.
1.01	15.00	.04	0.00	.04	1.02	15.10	235	.46	.43	.03	1801.
1.01	15.10	.03	0.00	.03	1.02	15.20	236	.76	.73	.03	1855.
1.01	15.20	.06	0.00	.06	1.02	15.30	237	1.37	1.34	.03	1955.
1.01	15.30	.10	0.00	.10	1.02	15.40	238	3.42	3.39	.03	2272.
1.01	15.40	.19	0.00	.19	1.02	15.50	239	.96	.96	.03	2841.
1.01	15.50	.05	.02	.05	1.02	16.00	240	.61	.58	.03	3610.
1.01	16.00	.05	.02	.05	1.02	16.10	241	.47	.44	.03	4263.
1.01	16.10	.04	.01	.04	1.02	16.20	242	.47	.44	.03	4533.
1.01	16.20	.04	.01	.04	1.02	16.30	243	.47	.44	.03	4450.
1.01	16.30	.04	.01	.04	1.02	16.40	244	.47	.44	.03	4103.
1.01	16.40	.04	.01	.04	1.02	16.50	245	.47	.44	.03	3628.
1.01	16.50	.04	.01	.04	1.02	17.00	246	.47	.44	.03	3126.
1.01	17.00	.04	.01	.04	1.02	17.10	247	.37	.34	.03	2772.
1.01	17.10	.03	.00	.03	1.02	17.20	248	.37	.34	.03	2509.
1.01	17.20	.03	.00	.03	1.02	17.30	249	.37	.34	.03	2293.
1.01	17.30	.03	.00	.03	1.02	17.40	250	.37	.34	.03	2102.
1.01	17.40	.03	.00	.03	1.02	17.50	251	.37	.34	.03	1943.
1.01	17.50	.03	.00	.03	1.02	18.00	252	.37	.34	.03	1811.
1.01	18.00	.03	.00	.03	1.02	18.10	253	.03	.00	.03	1688.
1.01	18.10	.00	0.00	.00	1.02	18.20	254	.03	.00	.03	1554.
1.01	18.20	.00	0.00	.00	1.02	18.30	255	.03	.00	.03	1379.
1.01	18.30	.00	0.00	.00	1.02	18.40	256	.03	.00	.03	1163.
1.01	18.40	.00	0.00	.00	1.02	18.50	257	.03	.00	.03	935.
1.01	18.50	.00	0.00	.00	1.02	19.00	258	.03	.00	.03	720.
1.01	19.00	.00	0.00	.00	1.02	19.10	259	.03	.00	.03	536.
1.01	19.10	.00	0.00	.00	1.02	19.20	260	.03	.00	.03	391.
1.01	19.20	.00	0.00	.00	1.02	19.30	261	.03	.00	.03	289.
1.01	19.30	.00	0.00	.00	1.02	19.40	262	.03	.00	.03	213.
1.01	19.40	.00	0.00	.00	1.02	19.50	263	.03	.00	.03	156.
1.01	19.50	.00	0.00	.00	1.02	20.00	264	.03	.00	.03	115.
1.01	20.00	.00	0.00	.00	1.02	20.10	265	.03	.00	.03	86.
1.01	20.10	.00	0.00	.00	1.02	20.20	266	.03	.00	.03	65.
1.01	20.20	.00	0.00	.00	1.02	20.30	267	.03	.00	.03	50.
1.01	20.30	.00	0.00	.00	1.02	20.40	268	.03	.00	.03	39.
1.01	20.40	.00	0.00	.00	1.02	20.50	269	.03	.00	.03	30.
1.01	20.50	.00	0.00	.00	1.02	21.00	270	.03	.00	.03	24.
1.01	21.00	.00	0.00	.00	1.02	21.10	271	.03	.00	.03	20.
1.01	21.10	.00	0.00	.00	1.02	21.20	272	.03	.00	.03	17.
1.01	21.20	.00	0.00	.00	1.02	21.30	273	.03	.00	.03	14.
1.01	21.30	.00	0.00	.00	1.02	21.40	274	.03	.00	.03	12.
1.01	21.40	.00	0.00	.00	1.02	21.50	275	.03	.00	.03	11.
1.01	21.50	.00	0.00	.00	1.02	22.00	276	.03	.00	.03	10.
1.01	22.00	.00	0.00	.00	1.02	22.10	277	.03	.00	.03	9.
1.01	22.10	.00	0.00	.00	1.02	22.20	278	.03	.00	.03	9.
1.01	22.20	.00	0.00	.00	1.02	22.30	279	.03	.00	.03	9.
1.01	22.30	.00	0.00	.00	1.02	22.40	280	.03	.00	.03	9.
1.01	22.40	.00	0.00	.00	1.02	22.50	281	.03	.00	.03	9.
1.01	22.50	.00	0.00	.00	1.02	23.00	282	.03	.00	.03	9.
1.01	23.00	.00	0.00	.00	1.02	23.10	283	.03	.00	.03	9.
1.01	23.10	.00	0.00	.00	1.02	23.20	284	.03	.00	.03	9.
1.01	23.20	.00	0.00	.00	1.02	23.30	285	.03	.00	.03	9.
1.01	23.30	.00	0.00	.00	1.02	23.40	286	.03	.00	.03	9.
1.01	23.40	.00	0.00	.00	1.02	23.50	287	.03	.00	.03	9.

1.02 0.00 144 .00 0.00 .00 2. 1.03 .10 289 0.00 0.00 0.00 9.  
 1.02 .10 145 .02 0.00 .02 2. 1.03 .20 290 0.00 0.00 0.00 9.  
 SUM 25.33 20.55 4.79 85641.  
 ( 643.)( 522.)( 122.)( 2425.08)

PEAK 6-HOUR 14-HOUR 72-HOUR TOTAL VOLUME  
 4533. 2099. 583. 295. 85670.  
 CMS 59. 17. 8. 2426.  
 INCHES 18.25 20.27 20.69 20.69  
 MM 463.43 514.94 525.49 525.49  
 AC-FT 1041. 1156. 1180. 1180.  
 THOUS CU M 1284. 1456. 1456.

\*\*\*\*\*

# HYDROGRAPH ROUTING

## ROUTING COMPUTATIONS

ISTAQ 2 ICOMP 1 IFCOR 0 ITAPE 0 JFLT 0 JFRT 0 INAME 1 IASTG 0 IAUQ 0  
 QLOSS 0.0 CLOSS 0.000 AVG 0.000 IKES 1 ROUTING DATA IOFT 0 IPMP 0 LSTR 0  
 MSTPS 1 NSTDL 0 LAG 0 AMSNK 0 X TSK STORA ISPRAT -1  
 STAGE 939.60 940.00 941.00 942.00 943.00 944.00 945.00 946.00  
 FLOW 0.00 19.00 61.00 105.00 163. 384. 548. 714. 883. 1055.  
 SURFACE AREA= 157. 158. 160. 163. 165. 168. 170. 173.  
 CAPACITY= 0. 63. 222. 384. 515. 548. 714. 883. 1055.  
 ELEVATION= 940. 940. 941. 942. 943. 944. 945. 946.

CREL SPWD COQ EXPW ELEV COOL CAREA EXPL  
 939.6 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
 TOFEL COQD EXPD DAMWID  
 942.8 0.0 0.0 0.0

END-OF-PERIOD HYDROGRAPH ORDINATES  
 MO. RA HR. MM PERIOD HOURS INFLOW OUTFLOW STORAGE STAGE  
 1.01 .10 1 .17 2. 0. 0. 939.6  
 1.01 .20 2 .33 2. 0. 0. 939.6  
 1.01 .30 3 .50 2. 0. 0. 939.6  
 1.01 .40 4 .67 2. 0. 0. 939.6  
 1.01 .50 5 .83 2. 0. 0. 939.6  
 1.01 1.00 6 1.00 2. 0. 0. 939.6  
 1.01 1.10 7 1.17 2. 0. 0. 939.6  
 1.01 1.20 8 1.33 2. 0. 0. 939.6  
 1.01 1.30 9 1.50 2. 0. 0. 939.6  
 1.01 1.40 10 1.67 2. 0. 0. 939.6  
 1.01 1.50 11 1.83 2. 0. 0. 939.6  
 1.01 2.00 12 2.00 2. 0. 0. 939.6

1.01	2.20	14	2.33	1.2	0.	0.	939.6
1.01	2.30	15	2.50	2.	0.	0.	939.6
1.01	2.40	16	2.67	2.	0.	0.	939.6
1.01	2.50	17	2.83	2.	0.	0.	939.6
1.01	3.00	18	3.00	2.	0.	0.	939.6
1.01	3.10	19	3.17	2.	0.	0.	939.6
1.01	3.20	20	3.33	2.	0.	0.	939.6
1.01	3.30	21	3.50	2.	0.	0.	939.6
1.01	3.40	22	3.67	2.	0.	0.	939.6
1.01	3.50	23	3.83	2.	0.	0.	939.6
1.01	4.00	24	4.00	2.	0.	0.	939.6
1.01	4.10	25	4.17	2.	0.	0.	939.6
1.01	4.20	26	4.33	2.	0.	0.	939.6
1.01	4.30	27	4.50	2.	0.	0.	939.6
1.01	4.40	28	4.67	2.	0.	0.	939.6
1.01	4.50	29	4.83	2.	0.	0.	939.6
1.01	5.00	30	5.00	2.	0.	0.	939.6
1.01	5.10	31	5.17	2.	0.	0.	939.6
1.01	5.20	32	5.33	2.	0.	0.	939.6
1.01	5.30	33	5.50	2.	0.	0.	939.6
1.01	5.40	34	5.67	2.	0.	0.	939.6
1.01	5.50	35	5.83	2.	0.	0.	939.6
1.01	6.00	36	6.00	2.	0.	0.	939.6
1.01	6.10	37	6.17	2.	0.	0.	939.6
1.01	6.20	38	6.33	2.	0.	0.	939.6
1.01	6.30	39	6.50	2.	0.	0.	939.6
1.01	6.40	40	6.67	2.	0.	0.	939.6
1.01	6.50	41	6.83	2.	0.	0.	939.6
1.01	7.00	42	7.00	2.	0.	0.	939.6
1.01	7.10	43	7.17	2.	0.	0.	939.6
1.01	7.20	44	7.33	2.	0.	0.	939.6
1.01	7.30	45	7.50	2.	0.	0.	939.6
1.01	7.40	46	7.67	2.	0.	0.	939.6
1.01	7.50	47	7.83	2.	0.	0.	939.6
1.01	8.00	48	8.00	2.	0.	0.	939.6
1.01	8.10	49	8.17	2.	0.	0.	939.6
1.01	8.20	50	8.33	2.	0.	0.	939.6
1.01	8.30	51	8.50	2.	0.	0.	939.6
1.01	8.40	52	8.67	2.	0.	0.	939.6
1.01	8.50	53	8.83	2.	0.	0.	939.6
1.01	9.00	54	9.00	2.	0.	0.	939.6
1.01	9.10	55	9.17	2.	0.	0.	939.6
1.01	9.20	56	9.33	2.	0.	0.	939.6
1.01	9.30	57	9.50	2.	0.	0.	939.6
1.01	9.40	58	9.67	2.	0.	0.	939.6
1.01	9.50	59	9.83	2.	0.	0.	939.6
1.01	10.00	60	10.00	2.	0.	0.	939.6
1.01	10.10	61	10.17	2.	0.	0.	939.6
1.01	10.20	62	10.33	2.	0.	0.	939.6
1.01	10.30	63	10.50	2.	0.	0.	939.6
1.01	10.40	64	10.67	2.	1.	1.	939.6
1.01	10.50	65	10.83	2.	1.	1.	939.6
1.01	11.00	66	11.00	2.	1.	1.	939.6
1.01	11.10	67	11.17	2.	1.	1.	939.6
1.01	11.20	68	11.33	2.	1.	1.	939.6
1.01	11.30	69	11.50	2.	1.	1.	939.6
1.01	11.40	70	11.67	2.	1.	1.	939.6
1.01	11.50	71	11.83	2.	1.	1.	939.6
1.01	12.00	72	12.00	2.	1.	1.	939.6
1.01	12.10	73	12.17	2.	1.	1.	939.6
1.01	12.20	74	12.33	2.	1.	1.	939.6
1.01	12.30	75	12.50	2.	1.	1.	939.6
1.01	12.40	76	12.67	2.	1.	1.	939.6
1.01	12.50	77	12.83	2.	1.	1.	939.6
1.01	13.00	78	13.00	2.	1.	1.	939.6

1.01	13.20	80	13.33	2.	1.	939.6
1.01	13.30	81	13.50	2.	1.	939.6
1.01	13.40	82	13.67	2.	1.	939.6
1.01	13.50	83	13.83	2.	1.	939.6
1.01	14.00	84	14.00	2.	1.	939.6
1.01	14.10	85	14.17	2.	1.	939.6
1.01	14.20	86	14.33	2.	1.	939.6
1.01	14.30	87	14.50	2.	1.	939.6
1.01	14.40	88	14.67	2.	1.	939.6
1.01	14.50	89	14.83	2.	1.	939.6
1.01	15.00	90	15.00	2.	1.	939.6
1.01	15.10	91	15.17	2.	1.	939.6
1.01	15.20	92	15.33	2.	1.	939.6
1.01	15.30	93	15.50	12.	1.	939.6
1.01	15.40	94	15.67	36.	1.	939.6
1.01	15.50	95	15.83	78.	1.	939.6
1.01	16.00	96	16.00	122.	3.	939.6
1.01	16.10	97	16.17	149.	3.	939.6
1.01	16.20	98	16.33	157.	7.	939.6
1.01	16.30	99	16.50	148.	?	939.7
1.01	16.40	100	16.67	131.	11.	939.7
1.01	16.50	101	16.83	107.	13.	939.7
1.01	17.00	102	17.00	89.	14.	939.7
1.01	17.10	103	17.17	76.	16.	939.7
1.01	17.20	104	17.33	65.	17.	939.7
1.01	17.30	105	17.50	55.	18.	939.7
1.01	17.40	106	17.67	46.	19.	939.7
1.01	17.50	107	17.83	38.	19.	939.7
1.01	18.00	108	18.00	31.	20.	939.7
1.01	18.10	109	18.17	26.	20.	939.7
1.01	18.20	110	18.33	18.	21.	939.7
1.01	18.30	111	18.50	14.	21.	939.7
1.01	18.40	112	18.67	11.	21.	939.7
1.01	18.50	113	18.83	9.	21.	939.7
1.01	19.00	114	19.00	7.	21.	939.7
1.01	19.10	115	19.17	6.	21.	939.7
1.01	19.20	116	19.33	6.	21.	939.7
1.01	19.30	117	19.50	6.	21.	939.7
1.01	19.40	118	19.67	6.	21.	939.7
1.01	19.50	119	19.83	6.	21.	939.7
1.01	20.00	120	20.00	6.	21.	939.7
1.01	20.10	121	20.17	6.	21.	939.7
1.01	20.20	122	20.33	6.	21.	939.7
1.01	20.30	123	20.50	6.	21.	939.7
1.01	20.40	124	20.67	6.	21.	939.7
1.01	20.50	125	20.83	6.	21.	939.7
1.01	21.00	126	21.00	6.	21.	939.7
1.01	21.10	127	21.17	6.	21.	939.7
1.01	21.20	128	21.33	6.	21.	939.7
1.01	21.30	129	21.50	6.	21.	939.7
1.01	21.40	130	21.67	6.	21.	939.7
1.01	21.50	131	21.83	6.	21.	939.7
1.01	22.00	132	22.00	6.	21.	939.7
1.01	22.10	133	22.17	6.	21.	939.7
1.01	22.20	134	22.33	6.	21.	939.7
1.01	22.30	135	22.50	6.	21.	939.7
1.01	22.40	136	22.67	6.	21.	939.7
1.01	22.50	137	22.83	6.	21.	939.7
1.01	23.00	138	23.00	6.	21.	939.7
1.01	23.10	139	23.17	6.	21.	939.7
1.01	23.20	140	23.33	6.	21.	939.7
1.01	23.30	141	23.50	6.	21.	939.7
1.01	23.40	142	23.67	6.	21.	939.7
1.01	23.50	143	23.83	6.	21.	939.7
1.02	0.00	144	24.00	6.	21.	939.7



1.02	.20	146	24.33	2.	6.	19.	939.7
1.02	.30	147	24.50	2.	6.	17.	939.7
1.02	.40	148	24.67	2.	6.	19.	939.7
1.02	.50	149	24.83	2.	6.	19.	939.7
1.02	1.00	150	25.00	2.	6.	19.	939.7
1.02	1.10	151	25.17	2.	6.	19.	939.7
1.02	1.20	152	25.33	2.	6.	19.	939.7
1.02	1.30	153	25.50	2.	6.	19.	939.7
1.02	1.40	154	25.67	2.	6.	19.	939.7
1.02	1.50	155	25.83	2.	6.	19.	939.7
1.02	2.00	156	26.00	2.	6.	19.	939.7
1.02	2.10	157	26.17	2.	6.	19.	939.7
1.02	2.20	158	26.33	2.	6.	19.	939.7
1.02	2.30	159	26.50	2.	6.	19.	939.7
1.02	2.40	160	26.67	2.	6.	19.	939.7
1.02	2.50	161	26.83	2.	6.	19.	939.7
1.02	3.00	162	27.00	2.	6.	19.	939.7
1.02	3.10	163	27.17	2.	6.	19.	939.7
1.02	3.20	164	27.33	2.	6.	18.	939.7
1.02	3.30	165	27.50	2.	6.	18.	939.7
1.02	3.40	166	27.67	2.	6.	18.	939.7
1.02	3.50	167	27.83	2.	6.	18.	939.7
1.02	4.00	168	28.00	2.	6.	18.	939.7
1.02	4.10	169	28.17	2.	6.	18.	939.7
1.02	4.20	170	28.33	2.	6.	18.	939.7
1.02	4.30	171	28.50	2.	5.	18.	939.7
1.02	4.40	172	28.67	2.	5.	18.	939.7
1.02	4.50	173	28.83	2.	5.	18.	939.7
1.02	5.00	174	29.00	2.	5.	18.	939.7
1.02	5.10	175	29.17	2.	5.	18.	939.7
1.02	5.20	176	29.33	2.	5.	18.	939.7
1.02	5.30	177	29.50	2.	5.	18.	939.7
1.02	5.40	178	29.67	2.	5.	18.	939.7
1.02	5.50	179	29.83	2.	5.	18.	939.7
1.02	6.00	180	30.00	2.	5.	18.	939.7
1.02	6.10	181	30.17	4.	5.	18.	939.7
1.02	6.20	182	30.33	9.	5.	18.	939.7
1.02	6.30	183	30.50	19.	5.	18.	939.7
1.02	6.40	184	30.67	34.	5.	18.	939.7
1.02	6.50	185	30.83	51.	6.	19.	939.7
1.02	7.00	186	31.00	68.	6.	19.	939.7
1.02	7.10	187	31.17	83.	6.	20.	939.7
1.02	7.20	188	31.33	94.	6.	21.	939.7
1.02	7.30	189	31.50	102.	7.	23.	939.7
1.02	7.40	190	31.67	108.	7.	24.	939.8
1.02	7.50	191	31.83	117.	8.	26.	939.8
1.02	8.00	192	32.00	116.	8.	27.	939.8
1.02	8.10	193	32.17	118.	9.	28.	939.8
1.02	8.20	194	32.33	120.	9.	30.	939.8
1.02	8.30	195	32.50	121.	10.	31.	939.8
1.02	8.40	196	32.67	122.	10.	33.	939.8
1.02	8.50	197	32.83	123.	10.	35.	939.8
1.02	9.00	198	33.00	123.	11.	36.	939.8
1.02	9.10	199	33.17	123.	11.	38.	939.8
1.02	9.20	200	33.33	124.	12.	39.	939.8
1.02	9.30	201	33.50	124.	12.	41.	939.9
1.02	9.40	202	33.67	124.	13.	42.	939.9
1.02	9.50	203	33.83	124.	13.	44.	939.9
1.02	10.00	204	34.00	124.	14.	45.	939.9
1.02	10.10	205	34.17	124.	14.	47.	939.9
1.02	10.20	206	34.33	124.	15.	48.	939.9
1.02	10.30	207	34.50	124.	15.	50.	939.9
1.02	10.40	208	34.67	124.	16.	51.	939.9
1.02	10.50	209	34.83	124.	16.	53.	939.9
1.02	11.00	210	35.00	124.	16.	54.	939.9

1.02	11.20	212	35.33	124.	17.	57.	940.0
1.02	11.30	213	35.50	124.	18.	59.	940.0
1.02	11.40	214	35.67	124.	18.	60.	940.0
1.02	11.50	215	35.83	124.	19.	62.	940.0
1.02	12.00	216	36.00	124.	19.	63.	940.0
1.02	12.10	217	36.17	139.	19.	65.	940.0
1.02	12.20	218	36.33	185.	20.	67.	940.0
1.02	12.30	219	36.50	283.	21.	70.	940.0
1.02	12.40	220	36.67	426.	22.	74.	940.1
1.02	12.50	221	36.83	588.	24.	81.	940.1
1.02	13.00	222	37.00	746.	26.	90.	940.2
1.02	13.10	223	37.17	887.	29.	101.	940.2
1.02	13.20	224	37.33	1007.	32.	113.	940.3
1.02	13.30	225	37.50	1106.	36.	127.	940.4
1.02	13.40	226	37.67	1195.	40.	143.	940.5
1.02	13.50	227	37.83	1275.	44.	159.	940.6
1.02	14.00	228	38.00	1344.	49.	176.	940.7
1.02	14.10	229	38.17	1404.	54.	195.	940.8
1.02	14.20	230	38.33	1463.	59.	214.	940.9
1.02	14.30	231	38.50	1528.	66.	233.	941.1
1.02	14.40	232	38.67	1601.	76.	254.	941.2
1.02	14.50	233	38.83	1676.	85.	275.	941.3
1.02	15.00	234	39.00	1745.	95.	298.	941.5
1.02	15.10	235	39.17	1801.	109.	321.	941.6
1.02	15.20	236	39.33	1855.	152.	344.	941.8
1.02	15.30	237	39.50	1955.	197.	368.	941.9
1.02	15.40	238	39.67	2272.	231.	394.	942.1
1.02	15.50	239	39.83	2841.	244.	426.	942.3
1.02	16.00	240	40.00	3610.	262.	467.	942.5
1.02	16.10	241	40.17	4263.	287.	517.	942.8
1.02	16.20	242	40.33	4533.	418.	573.	943.2
1.02	16.30	243	40.50	4450.	611.	628.	943.5
1.02	16.40	244	40.67	4103.	783.	677.	943.8
1.02	16.50	245	40.83	3628.	935.	719.	944.0
1.02	17.00	246	41.00	3126.	1104.	751.	944.2
1.02	17.10	247	41.17	2772.	1232.	776.	944.4
1.02	17.20	248	41.33	2509.	1330.	794.	944.5
1.02	17.30	249	41.50	2293.	1404.	809.	944.6
1.02	17.40	250	41.67	2102.	1458.	819.	944.6
1.02	17.50	251	41.83	1943.	1497.	827.	944.7
1.02	18.00	252	42.00	1811.	1524.	832.	944.7
1.02	18.10	253	42.17	1688.	1539.	835.	944.7
1.02	18.20	254	42.33	1554.	1545.	836.	944.7
1.02	18.30	255	42.50	1379.	1539.	835.	944.7
1.02	18.40	256	42.67	1163.	1521.	831.	944.7
1.02	18.50	257	42.83	935.	1488.	875.	944.7
1.02	19.00	258	43.00	720.	1443.	816.	944.6
1.02	19.10	259	43.17	536.	1387.	805.	944.5
1.02	19.20	260	43.33	391.	1323.	793.	944.5
1.02	19.30	261	43.50	289.	1255.	780.	944.4
1.02	19.40	262	43.67	213.	1185.	767.	944.3
1.02	19.50	263	43.83	156.	1116.	753.	944.2
1.02	20.00	264	44.00	115.	1048.	740.	944.2
1.02	20.10	265	44.17	86.	982.	728.	944.1
1.02	20.20	266	44.33	65.	919.	716.	944.0
1.02	20.30	267	44.50	50.	876.	704.	943.9
1.02	20.40	268	44.67	39.	837.	693.	943.9
1.02	20.50	269	44.83	30.	800.	682.	943.8
1.02	21.00	270	45.00	24.	764.	672.	943.7
1.02	21.10	271	45.17	20.	729.	662.	943.7
1.02	21.20	272	45.33	17.	695.	652.	943.6
1.02	21.30	273	45.50	14.	663.	643.	943.6
1.02	21.40	274	45.67	12.	634.	634.	943.5
1.02	21.50	275	45.83	11.	604.	624.	943.5
1.02	22.00	276	46.00	10.	574.	618.	943.4

1.02	22.20	278	46.33	9.	524.	943.3
1.02	22.30	279	46.50	9.	499.	943.3
1.02	22.40	280	46.67	9.	476.	943.3
1.02	22.50	281	46.83	9.	454.	943.2
1.02	23.00	282	47.00	9.	433.	943.2
1.02	23.10	283	47.17	9.	413.	943.1
1.02	23.20	284	47.33	9.	394.	943.1
1.02	23.30	285	47.50	9.	376.	943.1
1.02	23.40	286	47.67	9.	358.	943.1
1.02	23.50	287	47.83	9.	342.	943.0
1.03	0.00	288	48.00	9.	328.	943.0
1.03	.10	289	48.17	9.	316.	943.0
1.03	.20	290	48.33	9.	316.	942.9

PEAK OUTFLOW IS 1545. AT TIME 42.33 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1545.	1066.	321.	161.	46585.
44.	30.	9.	5.	1319.
INCHES	9.26	11.17	11.25	11.25
MM	235.32	283.81	285.75	285.75
AC-FT	528.	637.	642.	642.
THOUS CU M	652.	786.	791.	791.

\*\*\*\*\*

# RUNOFF SUMMARY, AVERAGE FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND) AREA IN SQUARE MILES(SQUARE KILOMETERS)

HYDROGRAPH AT	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
1	4533.	2099.	583.	295.	1.07
( 128.36)(	59.43)(	16.51)(	8.37)(	2.27)	
ROUTED TO	2	1545.	1066.	321.	1.07
( 43.74)(	30.18)(	9.10)(	4.55)(	2.77)	

## SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM		
	STORAGE	939.60	939.60	942.80		
	OUTFLOW	0.	0.	515.		
		0.	0.	283.		
RATIO	MAXIMUM	MAXIMUM	MAXIMUM	DURATION	TIME OF	TIME OF
OF	RESERVOIR	DEPTH	OUTFLOW	OVER TOP	MAX OUTFLOW	FAILURE
PHF	W.S.ELEV	OVER DAM	CFS	HOURS	HOURS	HOURS
0.00	944.72	1.92	1545.	8.33	42.33	0.00

\*\*\*\*\*  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION JULY 1978  
LAST MODIFICATION 26 FEB 79  
\*\*\*\*\*



MULTI-PLAN ANALYSIS TO BE PERFORMED

[illegible]

# COMPUTE HYDROGRAPH

ISTAQ	ICOMP	IECON	ITAPE	JCLT	JRET	NAME	STAGE	AUTO
1	0	0	0	0	0	1	0	0

		HYDROGRAPH DATA							
IHYDG	IUNG	TAREA	SNAP	CRSDA	IRSFCE	RATIO	ISPDW	NAME	LOCAL
1	2	1.07	0.00	1.07	.80	0.000	0	0	0

PRECIP DATA	
FMS	R6
SPFE	R12
22.30	112.00
0.00	123.00
	132.00
	142.00
	152.00
	162.00
	172.00
	182.00
	192.00
	202.00
	212.00
	222.00
	232.00
	242.00
	252.00
	262.00
	272.00
	282.00
	292.00
	302.00
	312.00
	322.00
	332.00
	342.00
	352.00
	362.00
	372.00
	382.00
	392.00
	402.00
	412.00
	422.00
	432.00
	442.00
	452.00
	462.00
	472.00
	482.00
	492.00
	502.00
	512.00
	522.00
	532.00
	542.00
	552.00
	562.00
	572.00
	582.00
	592.00
	602.00
	612.00
	622.00
	632.00
	642.00
	652.00
	662.00
	672.00
	682.00
	692.00
	702.00
	712.00
	722.00
	732.00
	742.00
	752.00
	762.00
	772.00
	782.00
	792.00
	802.00
	812.00
	822.00
	832.00
	842.00
	852.00
	862.00
	872.00
	882.00
	892.00
	902.00
	912.00
	922.00
	932.00
	942.00
	952.00
	962.00
	972.00
	982.00
	992.00
	1002.00

		LOSS DATA								
LPROPT	STRKR	DLTKR	RTIUL	ERAIN	STRKS	RTIOK	STRTL	CNSTL	ALSMX	WTIME
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.15	0.00	0.00

UNIT HYDROGRAPH DATA  
TC= 0.00 LAG= .80

```

RECESSION DATA
STRTO= -2.00  GRCSN= 0.00  RTIDR= 1.00

```

	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	CUMP Q
										SUM	25.33	20.55	4.79	85641.
										( 44 )	( 52 )	( 122 )	( 2425.08 )	

[illegible]

## HYDROGRAPH ROUTING

## ROUTING COMPUTATIONS

QLOSS	ISTAQ	ICOMP	IECON	IRATE	JFILT	JFRT	INAME	IMAGE	IAUTO
0.0	2	1	0	0	0	0	1	0	0
			ROUTING DATA						
	CLOSS	AVG	IRES	ISAME	IUPT	IPMF		LSTR	
0.0	0.000	0.000	1	0	0	0			
	NSTDL	LAG	AMSK		X	TSK	STORA	ISFRAT	
	1	0	0	0.000	0.000	0.000	0.	-1	

[illegible]

939.6 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
TOPEL 942.8  
COORD 0.0  
EXPD 0.0  
HAMWID 0.

PEAK OUTFLOW IS 104. AT TIME 43.33 HOURS  
PEAK OUTFLOW IS 236. AT TIME 43.17 HOURS  
PEAK OUTFLOW IS 278. AT TIME 43.17 HOURS  
PEAK OUTFLOW IS 477. AT TIME 43.00 HOURS  
PEAK OUTFLOW IS 722. AT TIME 42.83 HOURS

\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIO 5  
.30 .40 .50 .60 .70

HYDROGRAPH AT 1 1.07 1 1360. 1813. 2266. 2720. 3173.  
( 2.77) ( 38.51) ( 51.34) ( 64.18) ( 77.01) ( 89.85) (

ROUTED TO 2 1.07 1 104. 236. 278. 477. 722.  
( 2.77) ( 2.94) ( 6.67) ( 7.87) ( 13.51) ( 20.44) (

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 939.60 0. 0.	SPILLWAY CREST 939.60 0. 0.	TOP OF DAM 942.80 515. 283.	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO OF PHF	MAXIMUM RESERVOIR W.B.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS			
.30	941.58	0.00	316.	104.	0.00	43.33	0.00
.40	942.14	0.00	406.	236.	0.00	43.17	0.00
.50	942.73	0.00	503.	278.	0.00	43.17	0.00
.60	943.25	.45	590.	477.	4.67	43.00	0.00
.70	943.67	.87	660.	722.	6.67	42.83	0.00

\*\*\*\*\*  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION JULY 1978  
LAST MODIFICATION 26 FEB 79

**APPENDIX 4**

NOTES ON NEWTON, NEW JERSEY WATER WORKS  
CONSTRUCTION AND LITIGATION



# NEW ENGLAND WATER WORKS ASSOCIATION.

ORGANIZED 1882.

Vol. XXIII. June, 1909. No. 2.

*This Association, as a body, is not responsible for the statements or opinions of any of its members.*

## NOTES ON NEWTON, N. J., WATER WORKS CONSTRUCTION AND LITIGATION.

BY LOUIS L. TRIBUS, MEMBER AMERICAN SOCIETY CIVIL ENGINEERS;  
MEMBER NEW ENGLAND WATER WORKS ASSOCIATION.

[Read December 9, 1908.]

In 1894 the town of Newton, situated in the semi-mountainous region of the northwestern part of New Jersey, took up very actively the question of a public water supply. Rain water cisterns, shallow dug wells penetrating slightly into the slate rock, and an occasional driven or bored well but partially served the general needs of the community. An active contest was waged between interests desiring municipal ownership and those either wishing to secure a franchise or preferring that one be granted.

Early in the proceedings the writer was called upon to advise various committees, and later, when final decision called for municipal construction, to design the works and carry them to completion, and from time to time since then, to take up matters of operation and litigation.

Three sources of supply seemed possible: first, a driven-well pumping system close to the town, but subject to risk of contamination as the town developed; second, a lake of rather hard water, some four miles away, for which, also, pumping would be necessary. The third, recommended by the writer, and finally adopted, was Morris Lake, situated about eight miles in an air line from Newton, in depth from eight to one hundred and ten feet, somewhat increased over natural capacity by a low dam, and the

*Note.*—Among the illustrations in this paper occur a number reproduced through the courtesy of the Engineering Record.

surface at such an elevation as to permit of a flow by gravity and give a good serviceable pressure in all parts of Newton except one small high point and a portion of another hill lying chiefly outside the town limits. (Fig. 1.)

The source of supply thus selected was well-nigh ideal; a soft water; an uninhabited, mountainous, 85 per cent. wooded watershed (Fig. 1, Plate I). Unfortunately, however, for legal reasons, the lake was not tributary to a stream passing the town of Newton, but to one flowing in a different direction, so that Newton had no standing as a riparian owner.


The writer urged very strongly upon the Water Commissioners an amicable settlement with the mill owners on the stream below the lake before any work should be carried out, a settlement that could have been readily effected for a few hundred dollars apiece, probably not aggregating over two thousand dollars at the outside. Coupled with that advice it was still deemed advisable to provide increased storage facilities in Morris Lake, so that from storm flows alone there could be impounded an abundance of water for the needs of the town and thereby not interfere with the normal ordinary flow from the lake.

To this latter end a small brook, not entering the lake, but joining its outlet, far above the first mill (Titman's), was diverted by a masonry head gate (Fig. 2, Plate I) into a side hill ditch or canal (Fig. 1, Plate II) some three thousand feet or so in length, reaching a point just above the masonry dam, which was constructed at the outlet of the lake proper, at a site almost perfect for the purpose—a narrow neck with rock sides and bottom. To provide the additional storage, the dam was constructed of such a height as to raise the normal level of the lake about five feet, giving a flooded area of 155 acres, and in addition flash boards could be placed in the spillway, adding another two feet if desired. The total storage above the lower outlet thus secured amounted to 230,000,000 gallons, while the storage above the original normal high-water mark amounted to 208,000,000 gallons (Fig. 2, Plate II, and Fig. 1, Plate III).

As the combined watersheds thus made available equaled about three and one-half square miles, the estimated draft of 1,000,000 gallons per twenty-four hours could be easily provided several

Fig. 1.

NEWTON N.J. WATER WORKS  
PORTION OF NEW JERSEY TOPOGRAPHICAL MAP  
SHOWING  
WATERSHED, LAKE, CONDUIT LINE, TOWN & RESERVOIR  
ALSO  
SITES OF TITMAN'S, SPARKS & INGERSOLL'S MILLS



times over during the year from storm waters, which could not have been used through any existing developments by any mill on the stream (a tributary of the Wallkill River).

The Water Commission purchased the fee in Morris Lake (though not in the pond below the lake) and in a sufficient strip surrounding it to give reasonable protection and access; but in purchasing some of the land owned by the mill owner (J. B. Titman) next below the lake there was reserved to him the right to operate the gates in the artificial pond at the outlet of the main lake that had been in existence for many years and which because of the breaking down of an old dam between them had been, for a period, a part of it.

In the agreement, the town also bound itself to open the gate in the masonry dam so as to keep up the water level in the lower pond, thus practically leaving the control of the outflow in the hands of Titman, who had first right to use the waters, and who for many years had thus used the outflow from the lake and pond as he chose, without reference to any mill owners further down stream. Those lower owners had no pondage to do other than to steady the head upon their water wheels and, consequently, could not regulate the flow of the stream to any real extent for their own benefit, and also they had no special rights in the lake's storage or in control of its outflow.

Construction was carried on as previously outlined, without any formal objection from any mill owner. As a matter of fact, the mills were greatly benefited by the work done, for by the conservation of the storm waters, in excess of those which Newton could use, the stream flow was steadied, thus better meeting the needs of the mills than was possible prior to the construction.

The Water Commission did not take the advice of its engineer as to making agreements with the different mill owners, so that after the work was completed and the town was being supplied with water, several suits for damages for diversion of water were instituted, and these suits were pressed to final decision, the court of last resort, that of Errors and Appeals, confirming the decision of the Court of Chancery as to the principle involved, that payment must be made in money, as liquidated damages, instead of in kind, with water, but reversing the decision as to amount of

awards, cutting them down from \$3 180 to \$500 in one case, and from \$3 962.40 to \$750 in the other. The whole litigation, however, entailed an expense upon the town many times greater than would have been the case if preconstruction agreements had been entered into.

Early in 1902, J. B. Titman, the mill owner from whom the town had purchased some lands and rights, and to whom the privilege of gate opening had been accorded, as before noted, also brought suit for damages.

After litigation lasting several months, involving the attendance at the trials of many witnesses (experts and others), the case was compromised out of court by the town agreeing to pay said Titman \$5 500, receiving in return full control of the lake and Pine Swamp Brook (the one diverted to augment the Morris Lake supply) and use of all water which could flow through the existing 10-inch pipe line to Newton, and further agreeing to be careful in letting out the surplus lake waters, so as not to cause injury to the dam at lower end of pond adjoining the lake, and also to permit Titman to raise said earth dam up to within 4 feet of the level of the spillway in the masonry structure erected by the town.

Fig. 2, Plate III, shows the wastage of water from Titman's mill and the extravagant drafts he made on the stream and stored waters, after he contemplated bringing suit for damages, trying to create a shortage in storage, and show his great deprivation of water, presumably due to the town's use of it.

The main pipe line, 10 inches in diameter, was laid on an acquired right of way in as nearly as possible an air line, two or three summits being encountered, as may be noted on the profile (Fig. 2), where air valves were deemed advisable. At one place the summit




FIG. 2.

PLATE I.



FIG. 1.

PLATE II.



FIG. 1.




FIG. 2.

FIG. 2.



PLATE IV.



FIG. 1.

PLATE III.




FIG. 1.



FIG. 2.

## TRIUMPH.

- 149

so nearly approached the hydraulic grade line (taking the elevation of assumed average draft), as to become the controlling factor in the calculated flow of the main, as brought out in the court proceedings. The writer protested against laying any main less than 12 inches in diameter and urged the securing of rights of way, for later duplicating the line, if necessary, but the commissioners in their wisdom thought the ten or twelve thousand dollars' extra cost of the larger pipe prohibitive and the securing of additional rights unnecessary. Time has already demonstrated the wisdom of the engineer's advice, for the 10-inch main is well-nigh overtaxed, and needed rights for another main will require additional payments, while the water for the extra draft will have to be paid for by a new crop of damage suits, or through agreements to be entered into prior to its construction.

Though contemplated in the original scheme, the reservoir in the town was not constructed until 1905, when the draft had increased to such an extent as to make a twenty-four-hour flow necessary. This reservoir provides in its six or seven million gallons storage some little reserve in case of pipe line accident or stoppage, and secures a steadier fire service (Fig. 1, Plate IV).

## DETAILED DESCRIPTION OF PLANT.

The two lakes meet at a narrow strait, having a rock bluff at one side and a sloping rock ledge on the other. An old crib dam had formerly been in use, but years ago it was partially demolished. The rock banks met at a point 30 feet below the new high-water mark, or 33 feet below the top of the masonry, without injurious seams or cracks. The site could not have well been more advantageous, enabling a dam to be built only 150 feet long on the crest, with but 25 feet of it having any considerable depth.

Fig. 3 shows the general plan of headgate, canal, pond, lake, standpipe, and submerged outlet conduit.

The head-gate works for controlling the diversion canal consist of a small masonry dam and overflow weir, having two 24-inch gates opening into the canal. These openings will pass all of the normal and much of the flood season flow of the stream, and are located on Pine Swamp Brook about three thousand feet from and fourteen feet above the upper lake.




FIG. 3.


The deflection canal is 3,000 feet in length, following the general contour of the hill. It is 4 feet wide at the bottom, 2½ feet deep to the water run, and has slopes of 1½ to 1 in earth and ½ to 1 in rock. The canal was constructed in excavation entirely, so that the water run is everywhere in natural ground; the grade is 5 inches per 100 feet.

A timber cofferdam, about eight feet in width by nine feet in depth by sixty feet in length, was first built across the strait, 15 feet above the toe of the new dam, inclosing the end of the 12-inch effluent pipe, and provided with a 12 by 12-inch sluice to draw off water for the mills, if required. It was heavily framed, planked on both sides, its bottom shaped to the contour of the lake bed, steadied in place, and still further tightened by a double row of sheet piling driven to hard bottom. Clay and sand filling inside and on the upper lake side made a very tight structure, so that when the lower lake was drawn off and all the pressure came on one side, hand-pumping readily cared for all the seepage.

The main dam was constructed of local stone, a species of granite, laid as rough rubble, with rough dressed copings and spill-way, the sand for cement mortar being fine crushed rock from the Edison ore crushing works (Fig. 4). The flow line without flash boards was established at elevation 935 feet above sea level.


Adjoining the site of the dam, about five acres of land was secured for park purposes, and a commodious cottage was erected for the superintendent in charge of lake and conduit.

The conduit line is supplied through an intake standpipe in the lake and a submerged main carried along the bottom of the upper pond, through the masonry impounding dam and along the entire length of the lower pond and through the old dam at its lower end. The intake standpipe consists essentially of a wrought-iron open-ended cylinder 3½ feet in diameter and 38 feet in height, furnished with two 18-inch sluice gates opening at elevations 915½ and 922½, with conical brass screens inside, and connected with the 12-inch effluent pipe at elevation 912½. (Fig 5.) It was made with a reinforced cutting edge in the bottom and is protected by eight piles with cross and diagonal bracing of timber and sheathing, and some one hundred and fifty loads of riprap dropped around the foot.



Early in January, 1895, the ice having reached 12 inches in thickness, a point was selected (previous soundings having determined the approximate locality) where the silt bottom was 10 feet thick, and hard bottom found at elevation 900. A 40-foot derrick was then erected on the ice, its load distributed by a large plank platform, and the standpipe, bolted together, was raised complete, with 72 feet of 12-inch main attached, and lowered to position through a hole cut for it and a channel for the pipe. Its weight (about eight tons) caused it to sink several feet in the silt, cutting its way through; then by dredging from the inside and weighting, it was sunk into the hard bottom. When all the silt had been removed from the inside, Portland cement concrete was rammed in to a depth of 4 feet, giving additional stability and effectually shutting out all infiltration of silt. The piles were at once placed in similar manner with the derrick, and driven by it also, using a 1 500-pound hammer, with an 8-foot drop, guided by a scantling frame around the hammer long enough to pass down over the pile.

While the standpipe was being lowered, 72 feet of the 12-inch main connected to it was lowered also, in water 20 feet in depth, keeping the free end on top of the ice. To this was attached section after section, 48 feet being thereafter lowered at a time. A Ward spherical joint every 48 feet gave motion enough and rope supports in between kept the sections rigid, until they rested finally on the bottom. The upper lake section was 650 feet in length through the cofferdam. The lower lake section was about fourteen hundred feet to the lower earth dam. The depths ranged from six to twenty feet of water and zero to ten feet of silt. The work itself was very easily done, it being necessary simply to lay the pipe in a straight line on the ice, connect it up with lead joints, make a saw cut through the ice on each side of the line, the ice being from ten to fourteen inches in thickness, and lower the main gradually until it reached bottom, 48 feet at a time. At a later date when, during construction of the dam, the lower lake was emptied, the pipe was found resting easily, with no indications of break or strain. (Fig. 2, Plate IV.) It was thought best then to lower it from two to four feet to provide for a future complete draining of the lower lake, which was done by excavating underneath it and letting it settle.





The whole plant (including distribution system) was put in operation October 1, 1895, and was received from the commissioners by the town of Newton on October 17, 1895. The principal other dates of note were as follows:

December 3, 1894: contracts for  
(a) Pipe and specials to Warren Foundry and Machine Company.

(b) Valves and hydrants to Eddy Valve Company.

(c) Intake standpipe to Tippet & Wood.

December 18, 1894: contract for construction awarded to Smith & McCormick, of Easton, Penn.

January 14, 1895: construction begun.

May 8, 1895: contract for highway and bridge to B. H. Titman.

August 31, 1895: water turned into main pipe line.

September 19, 1895: water turned into canal, practically completing the construction period.

Officials connected with the work of construction:

Water Commissioners: Hiram C. Clark, president; Alex. Craig, secretary; A. J. Van Blarcom, treasurer.

Counsel: Chas. M. Woodruff.

Engineers: Louis L. Tribus, chief; Andrew H. Konkle, assistant on preliminary surveys; Chas. G. Massa, assistant on construction, lake division; B. F. Ward, assistant on pipe lines.

The work was completed within contract time, without material deviation from the plans and specifications, and for a total sum about one and a half per cent. less than the engineer's original estimate, the whole plant, without litigation, costing about one hundred and five thousand dollars for rights, lands, construction, supervision, and miscellaneous expenses.

The writer has thought the litigation to be of sufficient interest to warrant the presentation, not of the testimony given, but of the full decision of the court of last resort, which reviewed briefly the facts and gives clearly the argument and dictum:

New Jersey Court of Errors and Appeals, November Term, 1899. The Sparks Manufacturing Company, Respondent, v. The Town of Newton, Appellant; Worthington H. Ingersoll, Respondent, v. The Town of Newton, Appellant.

(1) When the riparian proprietor seeks the aid of a court of

equity to restrain the diversion of water by a municipal corporation for public purposes, and offers to forego his right to an injunction on recovering just compensation, which he asks the Court to determine, and the defendant in its answer consents to pay such compensation so as to be determined by the Court, in case the Court considers the complainant entitled to an injunction, the Court has jurisdiction to ascertain the amount of such compensation.

(2) A municipality which buys a piece of land on a private stream several miles from its corporate limits does not thereby become entitled as riparian owner to draw from the stream a supply of water for the inhabitants of the town.

(3) The town of Newton has no authority to divert water from private streams, to the detriment of lower riparian owners, on condition that it will store storm water and give it out into the streams in dry times, and thus confer a compensatory benefit on those owners, they not consenting thereto.

(4) In ascertaining just compensation for the diversion of water from a mill, the difference between the market value of the mill before the diversion and its market value afterwards is usually a simpler and safer criterion than estimates of the probable cost of producing by steam at the mill the power which the diverted water would supply and then estimates of the probable value of the water power at the mill, based on the rental value of power at other places more or less distant and dissimilar.

Messrs. W. H. and C. L. Corbin for complainants, respondents; Mr. Thomas Kays for defendant, appellant.

The opinion of the Court was delivered by Dixon, J.

The circumstances of these cases are very fully stated in the preface and opinion of Vice-Chancellor Pitney, 57 N. J. Eq. 367. With the conclusion there expressed touching the power and duty of the Court, on the pleadings and evidence, to fix the compensation, that the defendant ought to pay to the complainant as a condition of withholding the injunctions to which they otherwise would be entitled, this Court agrees. Only with respect to the amount awarded do we find reason for dissent.

The right to be obtained by the defendant under these decrees is the right to abstract from one of the tributaries of the Wallkill River a definite quantity of water, which in its natural course would flow past the complainant's mills. The opinion of the vice-chancellor deals with the right to divert 800 000 gallons per day, and this quantity of water is shown by him to be capable of producing 2.54 continuous horse-power at the Sparks Company's mill and 2.05 continuous horse-power at Ingersoll's mill. On

this basis the learned vice-chancellor proceeds with two calculations:

(1) To ascertain the probable annual cost of producing the same power by steam at these mill sites, and (2) to ascertain the probable annual value of the power at these localities, in view of the rental price of such power in other places more or less distant and dissimilar. Having thus formed an estimate of the annual value of the power, he compounds that value at 4 per cent. for forty years and finds the present value to be \$3 302 at the Sparks mill and \$2 650 at the Ingersoll mill, and, therefore, awards these sums.

In this course of reasoning little, if any, attention was paid to the actual market value of the mill sites, and yet in *Packard v. Bergen Neck R. R. Co.*, 25 Vroom, 553, this Court declared that, when only part of a person's property is taken, just compensation will be made by awarding the difference between the market value of the property before any part was taken and the market value of the property after the taking.

While it may be proper in such cases as the present to take into consideration the matters on which the vice-chancellor's award rests, still we deem the difference between market values a simpler and safer criterion; and when it appears that by following other guides a result is reached utterly irreconcilable with this criterion, that result cannot be sustained. That such incompatibility exists in the case before us will be made manifest by a few considerations now to be stated.

The testimony of witnesses living in the neighborhood of the Ingersoll mill and familiar with it for many years is to the effect that the fair market value of the whole plant in 1896 when these bills of complaint were filed was \$5 000 or \$6 000. It has a total capacity to use 132 horse-power of water, which will be furnished by about 1 100 000 gallons of water per month. A tabulated statement of the natural flow of the river at Ingersoll's mill, known in the case as Vermeule's Table D, which appears to have been accepted as trustworthy by all parties at the trial, shows that during eight months of the average year there is more than a sufficient supply of water for the full capacity of the mill, that during June and September the supply is above five sixths of the capacity, and that during July and August the supply exceeds five ninths of the capacity. These data indicate an annual supply equivalent to 113 continuous horse-power at this mill.

Now, if for the abstraction of 2.65 continuous horse-power the mill owner ought to be paid \$2 650 then, for the abstraction of the whole power he ought to be paid \$118 000. Such an inference proves the extravagance of the award. In April, 1890, the plant of the Sparks Manufacturing Company was purchased by that

company for \$75 000. The plant included the water machinery with a total capacity of 170 horse-power, steam machinery having 100 horse-power, mill buildings, and several acres of land.

To run the water plant to its full capacity the company required about 1 360 000 gallons of water per month, and beside it used about 30 000 000 gallons per month for condensing steam, washing fabrics, etc. Vermeule's Table D shows that during eight months of the average year there is more than a sufficient supply of water for the full capacity of this water power, that during June and September the supply is about two thirds of the capacity, and that during July and August the supply is about four ninths of the capacity. These data indicate an annual supply equivalent to 141 continuous horse-power at this mill.

If for the abstraction of 2.34 continuous horse-power of water the company ought to be paid \$3 302, then for the abstraction of the whole power it ought to be paid \$183 300. This inference proves the extravagance of the Sparks Company's award.

We think there is another error in the basis on which the present awards are made. Assuming that the defendant withdraws 800 000 gallons of water per day (i. e., 23 000 000 gallons per month), Vermeule's Table D shows that in an average year after the allowance to the defendant is taken, more water will flow past these mills during eight months than either of the mills can utilize, so that only during four months will the supply available in the mills be perceptibly diminished. During these months the water diverted by the town would furnish 3 horse-power at the mills, and 3 horse-power for four months would be equivalent to 1 continuous horse-power. Thus, even on the assumption that water power at these mills is as valuable as the learned vice-chancellor deemed it to be, allowances for 2.34 and 2.65 continuous horse-power are about two and one-half times too large.

In our judgment an award of \$500 to Mr. Ingersoll and of \$750 to the Sparks Manufacturing Company will afford ample compensation to them for the abstraction by the defendant of 800 000 gallons of water per day. Under the election by the town to abstract 1 250 000 gallons per day, these sums must be proportionately increased.

Let the present decree be reversed and decrease be rendered in accordance with the judgment above stated.

Notwithstanding this very lucid decision, the writer still holds very clearly to his belief that true justice should refuse to award damages where no actual damage has occurred or can occur, and where real benefit has been created instead. That argument is,

of course, met by the actual fact that water was diverted, so that theoretically the mills were deprived of it, and in light of a constitutional and not parliamentary government, payment can only be made in coin of the realm and must be based on theoretical as well as real injury.

Newton's case was at the time almost unique in the United States, where works of benefit were actually completed and in operation before litigation was begun, so that real damage could not be proven by inference or be shown in fact.

## DISCUSSION.

MR. CHARLES E. CHANDLER. At one or two meetings of the New England Water Works Association the question of compensating for diversion in kind, recommended in Norwich by Hill, Quick & Allen, has been referred to. I will read five or six lines which describe just the method in which Hill, Quick & Allen suggested that riparian owners be compensated for water that might be taken by the city. The proposition was to build a large storage reservoir, large enough to be ample for the city's needs with something left for the mill owners, but the actual proposition reads a little differently:

"Whenever the flow of the Yantic River at any of the mills from the watershed of that river above the mills, exclusive of the 11.9 square miles on Pease Brook, is less than the amount necessary to develop the flow at the mill, water is to be released from the proposed storage reservoir for the benefit of all the mills in quantities equal to the estimated flow of Pease Brook, at that time, but not exceeding the amount of the above deficiency."

That is the whole plan and, as you will see, it does not call for compensating the mills at all, but calls for a delivery to the mills, every day when they are short of water, the exact amount of water, as nearly as can be ascertained, that they would have received if this reservoir had not been built. The mill owners took it into consideration, and, having decided that the plan wasn't likely to go through for other reasons, declined to consider the proposition at all.

MR. WILLIAM S. JOHNSON. There was a case which interested

me very much, and it may interest water-works officials, which came up a few days ago, where a manufacturing company in a certain town was sued by the town for water rates, it being alleged that the company had been stealing water from the department. The result of that suit was that the town was obliged to pay the manufacturing company \$100 and court expenses. That seems a little peculiar, but the fact was that the water which had been furnished by the town to the manufacturing company had never been legally taken, but was being practically stolen from the manufacturing company, so you see there the tables were turned. This story carries its own moral.

VICE-PRESIDENT KING. The city of Taunton has had a case very similar to the one of which Mr. Tribus has spoken, and it was on trial last week. In 1875 an act of the legislature was passed which allowed the city of Taunton to take water from the Taunton River or from the Lakeville ponds. We first took it from the Taunton River, and in 1894 we went to the Lakeville ponds for water. The act of 1875 allowed us to take water from the Assowampsett Pond, but only the "surplus waters" of that pond, and required us to build a dam at the outlet, not less than two and one-half feet in height, — that is, there was an old mud sill there and this dam must be at least two and one-half feet above that old mud sill, — and we might store water for one year's supply of the city of Taunton, but we must maintain the natural flow of the stream.

There were some rather peculiar terms in the act. What the natural flow of the stream is it is hard to express; I suppose, in one sense that the natural flow is all the water that runs down that stream, but the Supreme Court has passed upon the act (100 Mass. 540) and said that it couldn't say just what the words meant, but that the intent was that we should let down during the dry season as much water as usually went down there, and we might store and use the water which came from thaws, freshets, and recent heavy rains.

The town of Middleboro owns part of the first water privilege below the lake, from which they get power to furnish electricity for the town of Middleboro. We took this water in July, 1891, and within a year they brought an action against us for diversion.

For eight years the suit was carried on the court records and no action taken by the town to bring the case to trial. In 1903 they began to move to get their money. The first action was heard by the county commissioners of Plymouth, and the city put in no defense, our attorney claiming that the town had not made out a case. The town put in its evidence and the county commissioners awarded \$2 000 damages. From this award the city of Taunton appealed.

A year or two afterwards Marcus Morton, Esq., of Boston, was appointed auditor by the court, and heard the case.

There is a little peculiarity in the deed of the water power to the town of Middleboro. The town is entitled to the use of the first 75 horse-power in that stream. If there is anything above that, I suppose that it is entitled to what it can get from the stream, but more than half of the dam belongs to some one else. There are two or three other opportunities to draw water, so that the amount of water the town could get over the 75 horse-power to which it is entitled would probably be small.

The auditor found that Taunton does not damage Middleboro if it is entitled to only 75 horse-power. If it is entitled to what they claimed, 125 horse-power (which was the development of their wheels), and if Taunton could operate its dam adversely to the interests of Middleboro, he estimated the damage at \$1 200; but if it was entitled to more than 125 horse-power he could not determine the damage, as there was no evidence submitted.

From this decision of the auditor the town of Middleboro appealed.

Mr. Freeman C. Coffin had been the engineer for the city of Taunton, and for four years made gagings on that stream, one year before the dam was built and three years afterward. His gagings showed that more water went down stream during the dry months after the dam was built than before. After Mr. Coffin's death the city of Taunton employed Mr. Metcalf as its engineer. There was a trial before a jury in Brockton in November, 1907, and the jury awarded the town \$12,000 damages. That, of course, includes interest, so the verdict would be about seven thousand dollars, and interest.

Judge King, of Springfield, presided, and he out the verdict down

to \$3 500, or he said that he would set the verdict aside unless the town of Middleboro would accept \$3 500, which they refused to do. Within the last two weeks the case has again been tried and the jury awarded \$13 241.50, about seventy-five hundred dollars and interest. A motion is being argued to-day to set that verdict aside. The case will undoubtedly go to the Supreme Court.

We take about two million gallons per day. That means 2.0 horse-power at this mill. When we first began we took about 1.5 horse-power. Mr. Coffin testified that the city of Taunton could take 10 000 000 gallons per day and still give the town of Middleboro during the dry months as much water as it had before we built the dam.

At the trial before the auditor, Mr. Allen, of Worcester, was the expert engineer for the town of Middleboro, and it then seemed to be the policy of the town to make out as large as possible the amount of water carried by the stream, and that we took all the water that they didn't get. At the last trial they changed their tactics and made the amount of flow of stream as small as possible.

Mr. LEONARD METCALF. Mr. King has set the facts admirably before you, but there is perhaps one other point to which I may call attention. I might say that of this 2½ feet in depth in storage over the ponds, the present consumption would correspond to from three to six inches, depending upon what ponds were included in the storage. There is an obligation in the taking of water from certain of the ponds by New Bedford as to the erection of weirs between the ponds, which results in limiting the flow, or determining the direction of the flow, at certain seasons of the year.

Furthermore, it may be of interest to add that it was estimated that the available power at this privilege was about seventy-five horse-power. At the time of the diversion, as Mr. King has stated, the diversion was about one and a half horse-power, and at the present time it is about two and six-tenths horse-power. The real estate experts put on by the town of Middleboro testified that the value of the entire plant, including the entire physical plant and its business as a going concern, the wires, dynamos, machinery, and so on, was \$70 000, and that it had cost, I think, \$63 000 as matter of fact about eight months before. In spite of that fact, the jury awarded the sum which Mr. King has stated for a diver-

sion at that time of 14 horse-power out of 75. The \$93,000 included a gas plant also, — a mere trifle.

Of course it seems very unjust from the point of view of equity, because as actually operated they are undoubtedly getting much more power to-day from that privilege with the water which is let down from storage during the dry months than they did before the construction of the dam, but the plaintiff laid great stress on the fact that the control of that storage was within the hands of Taunton. Of course it would be impossible for Taunton to hold this water up indefinitely; it has got to come down some time, and from a practical point of view it does not seem probable that Taunton would hold it up during the dry season to let it down in the wet season and encourage litigation. Compensation in kind, or compensation in storage of water, does not seem to have worked in this case.

APPENDIX 5  
REFERENCES

## APPENDIX 5

### REFERENCES MORRIS LAKE DAM

1. Brater, Ernest F. and Kings, Horace W. Handbook of Hydraulics 5th Edition, McGraw-Hill Book Company 1963.
2. United States Dept. of Agriculture, Soil Conservation Service, Somerset, N.J. Urban Hydrology for Small Watersheds, Technical Release No. 55, Jan 1975.
3. United States Dept. of Commerce Weather Bureau, April 1956, Hydrometeorological Report #33, Washington, D.C.
4. United States Dept. of Interior, Bureau of Reclamation Design of Small Dams, Second Edition 1973, Revised print 1977.
5. United States Dept. of Agriculture, Soil Conservation Service, Soil Survey of Sussex County and Morris County, August 1975.
6. United States Corps of Engineers, Flood Hydrograph Package (HEC-I), Davis, Calif., Sept 1978.
7. United Dept. of Agriculture, Soil Conservation Service, A Method for Estimating Volume and Rate of Runoff in Small Watersheds SCS-TP149, Revised April 1973.
8. United States Army Corps of Engineers, Recommended Guidelines for Safety Inspection of Dams, Washington, D.C.
9. Sauls, G. A., Additional Hydrology and Hydraulics Guidance, 12 September 1978.
10. Morris Lake Dam, High Stret Reservoir Dam, Phase I Inspection Report, Town of Newton, Newton, New Jersey, Cahn Engineers Inc., Wallingford, Connecticut, 1 March 1979.
11. Notes on Newton, N.J. Water Works Construction and Litigation, New England Water Works Association, Vol. 23, No. 2, June 1909.
12. New Jersey Department of Environmental Protection, Dam Application File No. 85, Morris Lake Dam.

